

Notes

1. Replacement brick to full depth of wall.
2. Extend timber cill to incorporate drip detail.
3. Cracked stone cill - consider pinning - to S.E. details.
4. Cracked brick - consider in-situ pinning. To S.E. details.
5. Redundant plant equipment removed and brickwork reinstated to match existing.
6. Clean and repair cast iron vent.

Repairs

- AtMB - Repair -Remove biological growth
- AtMB - Repair -Replace brick
- AtMB - Repair -Repointing
- AtMB - Repair -Stone indent or sacrificial mortar fill
- AtMB - Repair -Stone indent repair
- AtMB - Repair -Remove loose hard mortar with brush
- AtMB - Repair -Clean to remove guano deposits
- AtMB - Repair -Cracked brick. Mortar fill.
- AtMB - Repair -Mortar fill redundant fixing hole
- AtMB - Repairs -Clean off graffiti paint
- AtMB - Repair - Descale
- AtMB - Repair -Structural repair to S.E. details



REV | NOTE | DRN/CHK

Mosley Street


Proposed Elevation - Back
George Street - Repairs

PROJECT REF. 1995
DRWG NO. P(203)
REVISION
SCALE 1:100 @ A3
DATE 1st May 24
DRAWN HW

SK sketch E existing P proposed T tender C construction FI final issue

+44 161 236 0051
ARCHITECT@ATELIERMB.CO.UK

ATELIER.MB



1:100 @A3