

## **PHOTOGRAPHS**

**Heaton Park Farm Centre, Middleton Road, Manchester, M25 2SW**

**Re-roofing and External Repairs**

**Ref: AMP44649**



**Heaton Park Farm Centre**



Figure 1: View of the Front Elevation of the Heaton Park Farm Centre (Former Stable Block).




Figure 2: Aerial View of Roof Area 2 – Proposed Re-roofing



Figure 3: View of Existing Timber Guttering. Completely Rotted Through & Leaking.



Figure 4: View of Rotted / Missing Boarding to Courtyard Entrance Doors.



Figure 5: View of Rotted / Missing Boarding to Stable Block in Courtyard Area.



Figure 6: View of Rotted Timberwork to Cill of Vertically Sliding Sash Window.



Figure 7: View of Rot to Window.




Figure 8: View of Rot to Window Cill & Sash