



Photo from outside

Cracking and rot

GLAZING BAR mold and rot when too much moisture, swell and move from increased moisture content. (Cause of Condensation)



Photo from inside

REPLACE EXISTING SINGLE GLASS TO LIGHT WEIGHT ACRYLIC DOUBLE GLAZING"

GLAZING BAR (REPAIR OR REPLACE) TO MATCH

GLAZING BAR (REPAIR OR REPLACE) TO MATCH

RUBBER ROD

Thermal upgrading

Glazing section n.t.s.

NOTE :

- REMARK :
- 1.) NO unauthorized copying / reproduction permitted without expressed written permission.
 - 2.) The contractor shall check all dimensions and level on site before commencement of work.
 - 3.) No dimension to be scaled off this drawing.

LEGEND :

CLIENT :

PROJECT :
BARRACKS HOUSE
M15 4HA

DRAWING TITLE :
WINDOW INSPECTION
RECORD

DRAWN gw feb/22

CHKD -

SCALE AS SHOWN

00		
12		
11		
10		
09		
08		
07		
06		
05		
04		
03		
02		
01		
00		
rev	date	description

Revision / Version

DWG BH-P-001 00

JOB NO

GW GARYWONG WORKSHOP LIMITED

GARYWONG WORKSHOP LIMITED

100% Copyright Reserved. All Rights Reserved. No part of this drawing may be reproduced without written permission from Gary Wong Workshop Limited.