


[illegible]

MAIN ENTRANCE



A photograph showing the interior of a building that has suffered a major structural failure. A large section of the ceiling and upper walls has collapsed, leaving a massive pile of rubble, including bricks, concrete, and wooden beams, in the center of the room. To the left, a red metal staircase is visible, partially obscured by debris. On the right, a wooden frame structure, possibly for a roof or ceiling, remains standing but is exposed. In the foreground, a large arched window with multiple panes allows natural light into the space. Below the window, there are some chairs and a table, suggesting a classroom or meeting area. A sign with the words 'SUS ARE' is visible on a wall to the right. The overall scene is one of significant destruction and disrepair.

EXISTING PLASTERBOARD CEILING
REPAIRED MAJOR GYOOD INCLUDING
ALL MOULDINGS

EXISTING BEAM
ENCASED IN PLASTERBOARD
AND SKIM WITH NEW CHUNCE
EITHER SIDE

VOID OVER EXISTING CEILING
HOUSING EXISTING VENTILATION

NEW PLASTERBOARD
AND SKIM INFL TO FORM
SECULAR ROOM

4100

3000

EXISTING PLASTERBOARD CEILING

EXISTING WALL LINE CUT BACK FROM STEEL BEAM

4'0"

3'0"

CEILING PLAN-STRIP OUT			
DRAWN	NM	DATE	05-01-22
DRAWING NO.			2101-25
SCALE	1.50 @ A0	REV.	