

Appendix 9.5 Walkover Survey

A drain was depicted on the infrastructure plans. On a site visit, it appeared to be old surface water channel which could be from when the area was a railway. It was a dry brick structure, that was overgrown and covered by leaves. The start of the drain was difficult to locate but becomes barely visible moving 'upstream'. Photos featured below:





