



SURVEY & ENGINEERING PROJECTS

HEAD OFFICE:

3D Selby Place
Stanley Industrial Estate
Skelmersdale
Lancashire
WN8 8EF

info@sepsurvey.com • 01695 729835 • sepsurvey.com

2. Contents

1. Cover
2. Contents
3. Brief
4. Tools Used
5. Site Plan
6. Photographs
7. Video

3. Brief

Survey & Engineering Projects were asked to carry out a Dilapidation Survey of the Manchester Aquatics Centre, Manchester M13 9SS and the surrounding roads. The survey was to include photos and videos within the site showing existing damage in these areas as well as time related degradation, for example rust or rot. This information would then be compiled into a report to provide the client with a reference as to the condition of the area at this time.

It is beyond the scope of the survey to provide structural information of the site and the structures within it such as corrosion testing, creep, fatigue, stress or wear. This survey is only observational. Although every effort has been made to cover the area in detail, issues such as access will inevitably lead to some areas not covered. The survey was to only include areas that can be visible from the ground.


4. Equipment

- Sony Cyber-shot DSC-HX400V Digital Camera
- JVC Everio GZ-MG36EK Digital Camcorder

Surveyor: D Balmer

Date: 08/11/21

5. Site Plan



Please visit our website at www.sepsurvey.com

6. Photographs



DSC00582

Boundary Street East

Location: Road (West to East)

6. Photographs



DSC00583

Boundary Street East

Location: Road (West to East)

6. Photographs




DSC00584

Boundary Street East

Location: Road (West to East)

6. Photographs



DSC00585

Boundary Street East

Location: Road (West to East)

6. Photographs




DSC00586

Boundary Street East

Location: Road (West to East)

6. Photographs




DSC00587

Boundary Street East

Location: Road (West to East)

6. Photographs




DSC00588

Boundary Street East

Location: Road (West to East)

6. Photographs




DSC00589

Boundary Street East

Location: Road (West to East)

6. Photographs




DSC00590

Boundary Street East

Location: Road (West to East)

6. Photographs



DSC00591

Boundary Street East

Location: Road (West to East)

6. Photographs



DSC00573

Boundary Street East

Location: South Pavement (East
to West)

6. Photographs



DSC00574

Boundary Street East

Location: South Pavement (East
to West)

6. Photographs



DSC00575

Boundary Street East

Location: South Pavement (East
to West)

6. Photographs



DSC00576

Boundary Street East

Location: South Pavement (East
to West)

6. Photographs



DSC00577

Boundary Street East

Location: South Pavement (East to West)

6. Photographs




DSC00578

Boundary Street East

Location: South Pavement (East to West)

6. Photographs




DSC00579

Boundary Street East

Location: South Pavement (East
to West)

6. Photographs



DSC00580

Boundary Street East

Location: South Pavement (East to West)

6. Photographs



DSC00581

Boundary Street East

Location: South Pavement (East to West)

6. Photographs



DSC02123

6. Photographs



DSC02124

Boundary Street East

Location: South Pavement (East to West)

6. Photographs



DSC02125

Boundary Street East

Location: South Pavement (East
to West)

6. Photographs



DSC02126

Boundary Street East

Location: South Pavement (East
to West)

6. Photographs



DSC02127

Boundary Street East

Location: South Pavement (East
to West)

6. Photographs



DSC02128

Boundary Street East

Location: South Pavement (East
to West)

6. Photographs



DSC02129

Boundary Street East

Location: South Pavement (East
to West)

6. Photographs




DSC00592

Boundary Street East

Location: North Pavement (East
to West)

6. Photographs




DSC00593

Boundary Street East

Location: North Pavement (East to West)

6. Photographs




DSC00594

Boundary Street East

Location: North Pavement (East
to West)

6. Photographs




DSC00595

Boundary Street East

Location: North Pavement (East to West)

6. Photographs



DSC00596

Boundary Street East

Location: North Pavement (East
to West)

6. Photographs



DSC00597

Boundary Street East

Location: North Pavement (East to West)

6. Photographs



DSC00598

Boundary Street East

Location: North Pavement (East to West)

6. Photographs




DSC00599

Boundary Street East

Location: North Pavement (East
to West)

6. Photographs




DSC00600

Boundary Street East

Location: North Pavement (East
to West)

6. Photographs



DSC00601

Boundary Street East

Location: North Pavement (East
to West)

6. Photographs



DSC02130

6. Photographs



DSC02131

Boundary Street East

Location: North Pavement (East to West)

6. Photographs




DSC02132

Boundary Street East

Location: North Pavement (East to West)

6. Photographs



DSC02133

Boundary Street East

Location: North Pavement (East to West)

6. Photographs



DSC02134

Boundary Street East

Location: North Pavement (East
to West)

6. Photographs



DSC02135

Boundary Street East

Location: North Pavement (East to West)


6. Photographs



DSC02136

Boundary Street East

Location: North Pavement (East
to West)



SURVEY & ENGINEERING PROJECTS

HEAD OFFICE:

3D Selby Place
Stanley Industrial Estate
Skelmersdale
Lancashire
WN8 8EF

info@sepsurvey.com • 01695 729835 • sepsurvey.com