

Dear Sir/Madam,

02/09/2021

Application number 131070/FO/2021

Thank you for your response,

Firstly, I'd like to note out to you that prior to demolition the building was in a state of water leakage which caused mould to build up and was extremely unhealthy to us and our employees so therefore we were forced to demolish the side of the building as the building itself was starting to deteriorate itself as evidenced in the pictures instead. This posed a threat to our employees and ourselves. You can see from pictures already provided you there was no roof roof joists were exposed .The roof was no roof space for bats to inhabit themselves in so therefore I can confirm that there were no bats present prior to demolition. We hired professional people to carry out the demolition safely and in order to carry out the demolition safely the premises of our business was closed off to the public for a day.

This is the most information I could provide from the best of my knowledge, and I would be extremely grateful if you could complete this process as soon as possible.

If you do have any questions, feel free to contact me.

Regards,

K & M Body works