



E3P
Taylor Road
Urmston
Manchester
M41 7JQ

Manchester | London | Edinburgh

info@E3P.co.uk
www.E3P.co.uk

GAS MEMBRANE VALIDATION

Site: Bowes Street	
Date: 23-09-2020	Project Number: 11-813
Project Manager: R. Horseman	E3P Engineer: T. Preston
PM Qualifications: BSC(Hons) FGS Cenv	Engineer Qualifications: Verification of Gas Protection Systems July 18
Ground Gas Risk Assessment: Characteristic Situation 2 / Amber 1	
Overview: The membrane comprised Visqueen GX DPC wrapped under slab and spanned across internal and external walls which was taped to VOC block with GX jointing tape. E3P can confirm there were no punctures or tears at the time of inspection. Upon being laid the membrane was covered with a Celotex (closed Cell) floor insulation material which is considered to provide a high degree of protection. All external joints were inspected and E3P can confirm that the membrane was overlapped and double taped to external and internal gas resistant GX DPM. The membrane was taped to the gas resistant VOC Block DPM using a double-sided jointing tape. All the overlaps were then additionally taped using foil backed girth tape. Each unit has a service duct located to the front and outer edge of the property. E3P inspected each one and can confirm that the top hats have been adequately sealed against the membrane. Based on the information provided within this report, the site inspections and validation checklists, E3P can confirm that Plots 1-6 have been installed with gas protection measures in accordance with Characteristic Situation 2 to an acceptable level of workmanship. Based on the information provided within this report, the site inspections and validation checklists, E3P can confirm that Plots 1-6 have been installed with gas protection measures in accordance with Characteristic Situation 2 / Amber 1 to an acceptable level of workmanship.	
Membrane Specification: Hydrocarbon Resistant Membrane (VOC Blok and Visqueen GX)	



Plot – 1

General Condition of Membrane-Good Condition



Verification of Joints and Seals-Good Condition



Verification of Service Penetrations-Good Condition



Plot - 2


General Condition of Membrane-Good Condition



Verification of Joints and Seals-Good Condition



Verification of Service Penetrations-Good Condition



Verification of ventilation-Good Condition



Plot - 3

General Condition of Membrane-Good Condition



Verification of Joints and Seals-Good Condition



Verification of Service Penetrations-Good Condition



Verification of ventilation-Good Condition



Plot - 4

General Condition of Membrane-Good Condition



Verification of Joints and Seals-Good Condition



Verification of Service Penetrations-Good Condition



Verification of ventilation-Good Condition



Plot - 5


General Condition of Membrane-Good Condition



Verification of Joints and Seals-Good Condition



Verification of Service Penetrations-Good Condition



Verification of ventilation-Good Condition



Plot - 6

General Condition of Membrane-Good Condition



Verification of Joints and Seals-Good Condition



Verification of Service Penetrations-Good Condition



Verification of Ventilation-Good Condition





e3p

Gas Protection Validation Site Record

Plot No:

Inspection date/time:

23/9/20

Inspected by:

SJAMES

Photographed:

✓

✓ Notes/recommendations

Membrane Type Correct	✓	
Extent of Coverage Correct	✓	
Underside of Membrane	✓	
Slab / membrane condition	✓	
Laps and joints	✓	
Damp-proof course	✓	
Service entries	✓	
Folded Membrane Joint	✓	
Taped & Inspected	✓	

This Plot has **PASSED/FAILED** inspection. (Any proposed remedial works will be noted in the "Remarks" column on this form).

An additional inspection visit IS/IS NOT required for this Plot

Inspection by: *SJAMES* Signed: *SJAMES*

One record sheet to be completed for each plot - To be completed by E3P Professional Inspecting.



e3p

Gas Protection Validation Site Record

Plot No: 23/9/20

Inspection date/time:

23/9/20

Inspected by:

J JAMES

Photographed:

✓/x

✓

✓/x Notes/recommendations

Membrane Type Correct	✓	
Extent of Coverage Correct	✓	
Underside of Membrane	✓	
Slab / membrane condition	✓	
Laps and joints	✓	
Damp-proof course	✓	
Service entries	✓	
Folded Membrane Joint	✓	
Taped & inspected	✓	

This Plot has PASSED/FAILED* inspection. (Any proposed remedial works will be noted in the "Remarks" column on this form).

An additional inspection visit IS/IS NOT* required for this Plot.

Inspection by: J JAMES Signed: J JAMES

One record sheet to be completed for each plot - To be completed by E3P Professional Inspecting.



e3p

Gas Protection Validation Site Record

Pilot No:

Inspection date/time:

23/9/20

Inspected by:

SJAMES

Photographed:

✓

✓/x Notes/recommendations

Membrane Type Correct

✓

Extent of Coverage Correct

✓

Underside of Membrane

✓

Slab / membrane condition

✓

Laps and joints

✓

Damp-proof course

✓

Service entries

✓

Folded Membrane Joint

✓

Taped & inspected

✓

This Pilot has **FAILED** inspection. (Any proposed remedial works will be noted in the "Remarks" column on this form).


An additional inspection visit IS/IS NOT required for this Pilot.

Signed:

[Signature]

Inspection by: [Signature] Signed: [Signature]

One record sheet to be completed for each pilot - To be completed by E3P Professional Inspection.



Gas Protection Validation Site Record

Plot No:

Inspection date/time:

Inspected by:

Photographed:

✓/x Notes/recommendations

Membrane Type Correct ✓

Extent of Coverage Correct ✓

Underside of Membrane ✓

Slab / membrane condition ✓

Laps and joints ✓

Damp-proof course ✓

Service entries ✓


Folded Membrane Joint
Taped & inspected ✓

This Plot has PASSED "FAILED" inspection. (Any proposed remedial works will be noted in the "Remarks" column on this form).

An additional inspection visit IS/IS NOT* required for this Plot

Inspected by: Paul Jones Signed: [Signature]

One record sheet to be completed for each plot - To be completed by E3P Professional Inspecting.



Gas Protection Validation Site Record

Plot No: 534

Inspection date/time: 23/9/20	Inspected by: JAMES	Photographed: ✓/x ✓
-------------------------------	---------------------	---------------------

✓/x Notes/recommendations


Membrane Type Correct	✓
Extent of Coverage Correct	✓
Underside of Membrane	✓
Slab / membrane condition	✓
Laps and joints	✓
Damp-proof course	✓
Service entries	✓
Folded Membrane Joint Taped & inspected	✓

This Plot has PASS "FAILD" inspection. (Any proposed remedial works will be noted in the "Remarks" column on this form).

An additional inspection visit IS/IS NOT* required for this Plot

Inspection by: J. James (in day) Signed: J. James

One record sheet to be completed for each plot - to be completed by ESP Professional Inspecting.



Gas Protection Validation Site Record

Plot No. 633222

Inspection date/time: 23/9/20	Inspected by: JAMES	Photographed: ✓/x ✓
✓/x Notes/recommendations		
Membrane Type Correct	✓	
Extent of Coverage Correct	✓	
Underside of Membrane	✓	
Slabs / membrane condition	✓	
Laps and joints	✓	
Damp-proof course	✓	
Service entries	✓	
Folded Membrane Joint Taped & inspected	✓	
This Plot has PASSEDAILED* inspection. (Any proposed remedial works will be noted in the "Remarks" column on this form). An additional inspection visit IS/IS NOT* required for this Plot. Inspection by: J. JAMES Signed: J. JAMES One record sheet to be completed for each plot - To be completed by E3p Professional Inspecting.		