



Photo 1: Main entrance to the Active Lifestyles Centre at the corner of Denmark Road and Cecil Road.



Photo 2: Existing blue coloured high-level timber cladding and low-level concrete cladding panel at the car park elevations. Elevation numbers 3 and 4 on drawing reference ALC-MCC-B01-XX-DR-A-0013.



Photo 3: Existing blue coloured high-level timber cladding and low-level concrete cladding panel to the external elevation facing the football pitches. Elevation number 2 on drawing reference ALC-MCC-B01-XX-DR-A-0013.



Photo 4: High level flat timber cladding at elevation number 2 at junction with first floor fire escape stairs.



Photo 5: High level profiled timber cladding at elevation number 3.



Photo 6: High level profiled timber cladding at elevation number 4 at abutment to brick elevation



Photo 7: Internal view of the sports hall, showing the steel frame and roof structure.



Photo 8: Internal view of the high-level ventilation louver to the external wall of the sports hall.



Photo 9: Looking up at elevation number 2. This pic shows the covered ventilation louvers and the poor condition of the flat timber panelling at high level and stained concrete panels at low level.



Photo 10: Dirt stained low-level concrete panelling at elevation number 4.



Photo 11: Garage Outbuilding located adjacent to elevation number 3.



Photo 12: Remains of the existing fascia board to the garage outbuilding.



Photo 13: The damaged pebble dashed concrete render to the foot of the wall of the garage outbuilding.