


Additional Photos:



Historic patch undertaken as a result of previous leaks




Timbers and flashings over glazed roof to be inspected



Buddleia through the parapet. Possibly damaging stonework



Overgrown vegetation causing damage to brickwork and hopper



Entrance to Whitworth street



Historic flooding, aco drain not adequate



Lease plan of the station, detailing footbridge owned by TFGM