

Inspection report

Date : 29/03/2018	Job number :	Weather : no rain or snow	Operator : LEE M	Section number : 2	PLR SUFFIX: X
Weather no rain or snow	Vehicle : DK64 PNL	Camera : RCX90	Preset :	Cleaned : no	Operator : LEE M


Place : Road : Location Inspection	BELLE VUE BELLE VUE DOG TRACK Road MH1 (D/S) D/STREAM	Location details: Catchment: Tape number : Pipe Length	 0.30 m	U/S MH : U/S Depth : D/S MH : D/S Depth :	MH1 3.57 D/STREAM 0
Use: Year laid : Purpose : Total length :	Combined Routine inspection of condition 0.89 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 300 mm Vitrified clay 		

Comment :

1:50 Position
Depth: 3.57

Code Observation

Grade



0.8 m

MH	Start node type, manhole, reference number : MH1	0
WL	Water level, 10% of the vertical dimension	0
GP	General photograph taken at this point	0
DEX	Settled deposits, other, 30% cross-sectional area loss Remarks: BRICK	4
SA	Survey abandoned DEBRIS BRICK Remarks: DEX BRICK	0

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	1	5	5.6	5	5

Place :

Inspection pictures

Place :
BELLE VUE

Road :
BELLE VUE DOG TRACK

Date :
29/03/2018

Section number :
2

PLR Suffix :
X



Photo: 3_3_11_A.JPG
0.8m, General photograph taken at this point