

Service / Operational Defects (SRM 4)

Project name :
BELLE VUE TRACK

Project Number :

Contact :

Date :
29/03/2018

No.	PLR	Dir.	Use	Shape / Size	Date	Mat.	Total Length	Insp. Length	Peak HWG	Peak Score	Grade	Mean Score	Total Score
1	UP/STX	U	C	C 300	29/03/2018	VC	13.85	13.05	-	0	1	0	0
2	MH1X	D	C	C 300	29/03/2018	VC	0.89	0.09	-	5	5	5.6	5

Structural Defects (SRM 4)

Project name :
BELLE VUE TRACK

Project Number :

Contact :

Date :
29/03/2018

No.	PLR	Dir.	Use	Shape / Size	Date	Mat.	Total Length	Insp. Length	Peak HWG	Peak Score	Grade	Mean Score	Total Score
1	UP/STX	U	C	C 300	29/03/2018	VC	13.85	13.05	1	0	1	0	0
2	MH1X	D	C	C 300	29/03/2018	VC	0.89	0.09	-	0	1	0	0

Legend of Drawing:



WATER FLOW 1



Tree_Summer



SOAKAWAY: FOUL WATER



SURFACE WATER



PETROL INTERCEPTOR



RAINWATER PIPE



RODDING EYE



SOIL & VENT PIPE



SOAKAWAY: SURFACE WATER



W.C.



FOUL WATER



Tree_Winter



CESS PIT



GNDFLWC



SYPHON INTERCEPTOR



PIPE RUN



ROAD GULLY



SEPTIC TANK



COMBINED



GULLY



PUMP CH

Inspection report

Date : 29/03/2018	Job number :	Weather : no rain or snow	Operator : LEE M	Section number : 1	PLR SUFFIX: X
Weather no rain or snow	Vehicle : DK64 PNL	Camera : RCX90	Preset :	Cleaned : no	Operator : LEE M

Place : Road : Location Inspection	BELLE VUE BELLE VUE DOG TRACK Road MH1 (U/S) UP/ST	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	UP/ST 0 MH1 3.57
Use: Year laid : Purpose : Total length :	Combined Routine inspection of condition 13.85 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 300 mm Vitrified clay	

Comment :

1:120 Position
Depth: 3.57

Code Observation

Grade



13.85 m

MH1

0.80

MH Start node type, manhole, reference number :
MH1

0

0.80

WL Water level, 05% of the vertical dimension

0

0.80

GP General photograph taken at this point

0

7.95

S01 JDM Joint displaced, medium, Start

1

13.85

GP General photograph taken at this point Remarks:
DEBRIS IN DISTANCE

0

13.85

F01 JDM Joint displaced, medium, End

1

13.85

SA Survey abandoned JDM Remarks: JDM

0



STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	0	0	0	0	1

Place :

Inspection pictures

Place :
BELLE VUE

Road :
BELLE VUE DOG TRACK

Date :
29/03/2018

Section number :
1

PLR Suffix :
X



Photo: 1_1_6_A.JPG

13.85m, General photograph taken at this point Remarks:
DEBRIS IN DISTANCE