

2.3 Site Photographs - Existing Building



Key Plan




Ground level of Tower on North elevation




View looking south east onto west machine hall



Existing condition of mini-mosaic tiles to south elevation at ground level




View looking up to tower; original joint lines visible; areas of mosaic delamination and remediation apparent.



View looking up to existing facade from rooftop car park



View looking east along Crumps Vale



View within recessed entrance area to south elevation, showing mosaics to soffit and walls.