



Block B- Rear View
2x 2b3p Double Storey Dwellings



1. Light red brick, Istobck Ivanhoe Mellow Red, sand coloured natural mortar.
2. Dark red brick, Istobck Ivanhoe (Broadgate) Claret, sand coloured natural mortar.
3. Munster Triple glazed Passivhaus Certified Window Units(PassivUPVC). RAL 7015 (natural white internally).
4. Red slim edge concrete roof tiles, Marles Edgeless old English.
5. Wetcast stone heavy panel cl in buff/natural. Head with sawtooth mortar.
6. UPVC linear type roof flashing, dark grey colour.
7. Sawtooth brick intermediate panel in matching brick.
8. Setback brick panel reveal detail.
9. UPVC downpipes and gutters, with matching fascia, dark grey colour (gutters to be square profile per S80 requirements)
10. Wetcast stone surrounds to key entrances in buff/natural.

					GWP Ref		(299)1926					
C05	12.04.21	MVHR External wall grilles update and bat box location	CT	DT	Job Title	Blackrock Street		Block B - Phase 1				
C04	01.03.21	Brick piers added to driveway/ fencing update	CT	DT								
C03	28.10.20	ASHP intake/extract location	CT	DT								
C02	23.10.20	Fencing update	CT	DT								
C01	18.08.20	Construction issue	CT	DT								
P03	11.05.20	Proposed roof intake/extract	CT	DT	Client							
Rev	Date	Comment	Dr	Ch		Name		1926-GWP-02-ZZ-DRA-A-(00)-0041				
						Scale		1:100@A1		Revision		C05
						Drawn/Checked		JA / DT		First Issue		28.02.20
						Working Status		A - Construction				
Revision: 02/10/2014 - BMS based for ARCHCAD 24/7/2014 (299)1914 02/01/21 - 10A Manchester Group P13												
Drawn/Checked: JA / DT												
Working Status: A - Construction												
Broken House Leeds LS8 1YQ UK +44(0)1132640646 +44(0)1132641859 chartered@gwp-group.com www.gwp-group.com												