



Photo 1: St James Church cracking to Parapet Wall damaged by growth of Goat Willow.



Photo 2: Parapet wall section to be rebuilt to best match existing.



Photo 3: Remains of the Goat Willow stump to the joint of the parapet / retaining wall.



Photo 4: Goat Willow stump showing Ecoplugs treatment used to prevent further growth.



Photo 5: Existing Headstone positioned against parapet wall section that requires rebuilding.



Photo 6: Retaining wall (photo taken prior to Goat Willow treatment).



Photo 7: Existing tarmac pathway adjacent to wall.



Photo 8: Existing headstones at burial grounds adjacent to the boundary wall.



Photo 9: Temporary fencing to prevent public access to damaged wall areas



Photo 10: Vegetation overgrowth that requires removal from both sides of wall.



Photo 11: Section of parapet wall to be repaired and repointed.



Photo 12: Section of parapet wall to be repaired and repointed



Photo 13: Existing parapet wall condition, showing spalling brickwork and loose pointing



Photo 14: Existing coping stone joint.