



CIS Tower,
Miller Street,
Manchester.
M60 0AL.

CIS Tower Refurbishment.

Recording Strategy and Photographic Audit of internal & external features.

APPENDIX 32 – Roof Level.

Planning Permission ref: 126118/FO/2020. Condition 29.

&

LBC ref: 126119/LO/2020. Condition 10.

Prepared by:



Stephen Levrant Heritage Architecture Ltd
Canada House, Suite 1.6
3 Chepstow Street
www.heritagearchitecture.co.uk

Prepared for:

Devonshire (CIS Tower) Ltd.
27 October 2020.



CIS Tower. Appendix 32 – Roof Level Recording Strategy and Photographic Audit of internal features, 2020.

All rights reserved.

Copyright © Stephen Levrant: Heritage Architecture Ltd.

Whilst copyright of this report as a whole is vested in Stephen Levrant: Heritage Architecture Ltd., copyright of individual contributions regarding sections of referenced works belongs to their respective authors, and no part may be reproduced, transmitted, stored in a retrieval system in any form or by any means whether electronic, mechanical, via photocopying, recording or otherwise, without the previous consent of the author.

Stephen Levrant: Heritage Architecture Ltd.

Document production © Stephen Levrant: Heritage Architecture Ltd 2020.

Draft Issued: 24 September 2020

Issued: 27 October 2020

Heritage Architecture Ltd is Registered in England, Number 3053944 • VAT GB656883581.

Registered office: 5 Technology Park, Colindeep Lane, Colindale, London NW9 6BX

Correspondence to be addressed to 62 British Grove, London, W4 2NL; or: Suite 1.06, Canada House, Chepstow Street, Manchester M1 5FW

FLOOR LEVEL Roof Plant and lift over-run.**Roof Level. Context and general character.**

- i) The open roof on the roof above the main office tower is a plant area accessed from stairs leading from Level 25. The roof deck was (photographed on 16 September 2020).
- ii) The plant deck is screened by a raised parapet, with plant set within the window cleaning tracks. The floor plan has been altered from its original 1962 open-plan form by means of the movement and addition of office partitions.
- iii) The glazing of the glazed pyramid lights has been altered and the plant has also been updated since 1962. Refer to the below plan, Figure 1 for the location and direction of views.



RL-01 Looking south from the parapet, showing the details of the applied signage and photovoltaic cells as well as the track access to the lift tower.



RL-02 Looking south-west from the parapet showing the track-bed for the window access plant and glazed pyramid roof lighting the west-side of level 25 below.



RL-03 Looking south-east from the parapet showing the track-bed for the window access plant and glazed pyramid roof lighting the east-side of level 25 below.



RL-04 Looking north from the south parapet showing detail of the structure of the glazed pyramid roof.



RL 05 Detail of the original upstand and clerestory glazing of the pyramid roof, showing the failing, applied protective film.



RL-06 Looking south-west from the south-east corner at the detail of the cladding of the service tower and signage.



RL-07 Looking south showing the detail of the parapet, lightning conductor, photovoltaic panels and lower level cladding.



RL-08 Looking up the service tower to the coffered concrete roof above the lift overrun.



RL-09 Detail of stairs to the service tower roof.




Figure 1 . The location and direction of the views discussed above.



CIS

Co-operative Insurance

Stephen Levrant Heritage Architecture Ltd
CONSERVATION ARCHITECTS & HERITAGE CONSULTANTS

London. 62 British Grove, Chiswick, 0208 748 5501 (Tel)
Manchester. Canada House, 3 Chepstow Street, M1 5FW 0161 247 8335 (Tel)