



Photo 1: Photograph taken on Stenner Lane facing the Western perimeter boundary retaining wall to Fletcher Moss Art Gallery. Photo shows section of wall to be dismantled and rebuilt adjacent the large Field Maple Tree.



Photo 2: Root system at ground level and parapet wall from inside Parsonage Gardens.



Photo 3: Photograph shows pier adjacent Field Maple tree and the two different brick bonds either side, English Garden Wall bond and Stretcher bond.



Photo 4: Photograph of the leaning boundary / retaining wall. Photo shows the roots behind the wall are pushing the wall at parapet level.



Photo 5: Photograph shows the cast insitu concrete coping on top of the boundary wall and tree roots growing between the brick mortar joints.



Photo 6: Roots at ground / footpath level at base of pier adjacent Field Maple Tree.



Photo 7: Photograph shows the existing copings, left side newer concrete coping, pier coping and original curved coping on right hand side.



Photo 8: Photograph shows the parapet wall section on the Parsonage Garden side.



Photo No.9: Photograph shows the section of wall between the two piers with original coping stones.



Photo No.10: Photograph shows the existing pier coping.