



Project

Project Name: 123 LEVENSHULME ROAD GORTON MAIN LINES

Project Date: 13/05/2025

Inspection Standard: MSCC5 Sewers & Drainage GB (SRM5 Scoring)



Table of Contents

Project Name	Project Number	Project Date
123 LEVENSHULME ROAD GORTON MAIN LINES		13/05/2025

Project Information	P-1
Section Item 1: S11 > S12 (S11X)	1
Section Item 2: S12 > S16 (S12X)	2
Section Item 3: S18 > S24 (S18X)	3
Section Item 4: S19 > S20 (S19X)	4
Section Item 5: S20 > S23 (S20X)	5
Section Item 6: S23 > S24 (S23X)	6
Section Item 7: S24 > TANK (S24X)	7



Project Information

Project Name	Project Number	Project Date
123 LEVENSHULME ROAD GORTON MAIN LINES		13/05/2025



Section Inspection - 13/05/2025 - S11X

Item No.	Insp. No.	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
1	1	13/05/25	11:21	Not Specified	Not Specified	Not Specified	S11X
Operator		Vehicle		Camera	Preset Length	Legal Status	Alternative ID
Not Specified		Not Specified		Not Specified	Not Specified	Not Specified	Not Specified

Town or Village:		Inspection Direction:	Downstream	Upstream Node:	S11
Road:		Inspected Length:	30.33 m	Upstream Pipe Depth:	
Location:		Total Length:	30.33 m	Downstream Node:	S12
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use:	Surface water			Pipe Shape:	Circular
Type of Pipe:				Dia/Height:	375 mm
Flow Control:				Material:	Polyvinyl chloride
Year Constructed:	Not Specified			Lining Type:	No Lining
Inspection Purpose:				Lining Material:	No Lining

Comments:
Recommendations:

Scale:	1:263	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: m S11 0.00 MH Start node, manhole, reference: S11 12.68 CN Connection other than junction at 1 o'clock, 150mm dia 17.90 CN Connection other than junction at 9 o'clock, 150mm dia 24.17 CN Connection other than junction at 1 o'clock, 150mm dia 30.33 MHF Finish node, manhole, reference: S12 S12 Depth: m							

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection - 13/05/2025 - S12X

Item No. 2	Insp. No. 1	Date 13/05/25	Time 11:27	Client's Job Ref Not Specified	Weather Not Specified	Pre Cleaned Not Specified	PLR S12X
Operator Not Specified		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Downstream	Upstream Node: S12
Road:	Inspected Length: 33.32 m	Upstream Pipe Depth:
Location:	Total Length: 33.32 m	Downstream Node: S16
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 375 mm	
Flow Control:	Material: Polyvinyl chloride	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose:	Lining Material: No Lining	

Comments:
Recommendations:

Scale: 1:289	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: m S12						
	0.00	MH	Start node, manhole, reference: S12			
	6.17	CN	Connection other than junction at 1 o'clock, 150mm dia			
	20.40	CN	Connection other than junction at 9 o'clock, 150mm dia			
	21.66	CN	Connection other than junction at 1 o'clock, 150mm dia			
	33.32	MHF	Finish node, manhole, reference: S16			
S16 Depth: m						

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0




Section Inspection - 13/05/2025 - S18X

Item No. 3	Insp. No. 1	Date 13/05/25	Time 11:31	Client's Job Ref Not Specified	Weather Not Specified	Pre Cleaned Not Specified	PLR S18X
Operator Not Specified		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Downstream	Upstream Node: S18
Road:	Inspected Length: 3.00 m	Upstream Pipe Depth:
Location:	Total Length: 3.00 m	Downstream Node: S24
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 375 mm	
Flow Control:	Material: Polyvinyl chloride	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose:	Lining Material: No Lining	

Comments:
Recommendations:



Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection - 13/05/2025 - S19X

Item No.	Insp. No.	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
4	1	13/05/25	11:37	Not Specified	Not Specified	Not Specified	S19X
Operator		Vehicle		Camera	Preset Length	Legal Status	Alternative ID
Not Specified		Not Specified		Not Specified	Not Specified	Not Specified	Not Specified

Town or Village:	Inspection Direction: Downstream	Upstream Node: S19
Road:	Inspected Length: 16.73 m	Upstream Pipe Depth:
Location:	Total Length: 16.73 m	Downstream Node: S20
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 375 mm	
Flow Control:	Material: Polyvinyl chloride	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose:	Lining Material: No Lining	

Comments:
Recommendations:

Scale: 1:145	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: m S19						
	0.00	MH	Start node, manhole, reference: S19			
	5.70	CN	Connection other than junction at 11 o'clock, 150mm dia			
	8.10	CN	Connection other than junction at 1 o'clock, 150mm dia			
	8.97	CN	Connection other than junction at 1 o'clock, 150mm dia			
	16.73	MHF	Finish node, manhole, reference: S20			
S20 Depth: m						

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0




Section Inspection - 13/05/2025 - S20X

Item No.	Insp. No.	Date	Time	Client's Job Ref	Weather	Pre Cleaned	PLR
5	1	13/05/25	11:40	Not Specified	Not Specified	Not Specified	S20X
Operator		Vehicle		Camera	Preset Length	Legal Status	Alternative ID
Not Specified		Not Specified		Not Specified	Not Specified	Not Specified	Not Specified

Town or Village:		Inspection Direction: Downstream		Upstream Node: S20	
Road:		Inspected Length: 13.77 m		Upstream Pipe Depth:	
Location:		Total Length: 13.77 m		Downstream Node: S23	
Surface Type:		Joint Length:		Downstream Pipe Depth:	
Use: Surface water			Pipe Shape: Circular		
Type of Pipe:			Dia/Height: 375 mm		
Flow Control:			Material: Polyvinyl chloride		
Year Constructed: Not Specified			Lining Type: No Lining		
Inspection Purpose:			Lining Material: No Lining		

Comments:
Recommendations:



Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0



Section Inspection - 13/05/2025 - S23X

Item No. 6	Insp. No. 1	Date 13/05/25	Time 11:41	Client's Job Ref Not Specified	Weather Not Specified	Pre Cleaned Not Specified	PLR S23X
Operator Not Specified		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Downstream	Upstream Node: S23
Road:	Inspected Length: 11.23 m	Upstream Pipe Depth:
Location:	Total Length: 11.23 m	Downstream Node: S24
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 375 mm	
Flow Control:	Material: Polyvinyl chloride	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose:	Lining Material: No Lining	

Comments:
Recommendations:

Scale: 1:98	Position [m]	Code	Observation	MPEG	Photo	Grade
Depth: m S23 0.00 MH Start node, manhole, reference: S23						
8.95 CN Connection other than junction at 12 o'clock, 150mm dia						
11.23 MHF Finish node, manhole, reference: S24						
S24 Depth: m						

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0




Section Inspection - 13/05/2025 - S24X

Item No. 7	Insp. No. 1	Date 13/05/25	Time 11:43	Client's Job Ref Not Specified	Weather Not Specified	Pre Cleaned Not Specified	PLR S24X
Operator Not Specified		Vehicle Not Specified		Camera Not Specified	Preset Length Not Specified	Legal Status Not Specified	Alternative ID Not Specified

Town or Village:	Inspection Direction: Downstream	Upstream Node: S24
Road:	Inspected Length: 0.91 m	Upstream Pipe Depth:
Location:	Total Length: 0.91 m	Downstream Node: TANK
Surface Type:	Joint Length:	Downstream Pipe Depth:
Use: Surface water	Pipe Shape: Circular	
Type of Pipe:	Dia/Height: 375 mm	
Flow Control:	Material: Polyvinyl chloride	
Year Constructed: Not Specified	Lining Type: No Lining	
Inspection Purpose:	Lining Material: No Lining	

Comments:
Recommendations:

Scale: 1:50	Position [m]	Code	Observation	MPEG	Photo	Grade
						
	0.00	MH	Start node, manhole, reference: S24			
	0.91	BRF	Finish node, major connection without manhole, reference: TANK			

Construction Features					Miscellaneous Features				
Structural Defects					Service & Operational Observations				
STR No. Def	STR Peak	STR Mean	STR Total	STR Grade	SER No. Def	SER Peak	SER Mean	SER Total	SER Grade
0	0.0	0.0	0.0	1.0	0	0.0	0.0	0.0	1.0