

Project 2045 | Midland West Entrance - Fire
Issued

NO.	TYPE	NBS REF.	LOCATION	DETAILS	DATE	AGREED WITH ARCHITECT	AGREED WITH PLANNER/CO
2	Doff clean of terracotta	C40. See Bullen methodology document.	Front elevation	Lowest pressure required. Needs to be soaked for 1-2 days before DOFF treatment, and use of mild handheld abrasive pad.	24-12-10	Y	Y - Paul Mason.

Image 1	Image 2
	