



Photograph 1 – circa 1980s



Photograph 2 – circa 1980s



Photograph 3 – Head connection with internal column



Photograph 4 – Head connection with internal column with removable lead spigot and upvc lining pipe visible



Photograph 5 – base of column with upvc lining pipe visible



Photograph 6 – existing / current arrangement of transition pipe into internal lining pipe



Photograph 7 – installed independent downpipe, concealed behind column to the west side



Photograph 8 – view from south within cover platform, showing new cast iron downpipe fixed into the side of existing column



Photograph 9 – view from the west, looking east, showing new cast iron independent downpipe, dispersing into south trough



Photograph 10 – final sample of new cast iron downpipe including finish and bracketing



Photograph 11 – final sample of new cast iron downpipe including finish and bracketing