



BH | SIM SITEWIDE - Gantry | **Secondary Frame Repair (Type 8 Repair)**

THIS SKETCH COVERS THE PROPOSAL FOR A STEEL REPAIR FOR AN ELEMENT OF SECONDARY FRAMING ON THE GANTRY LOCATED TO THE NORTH FACE OF THE NORTH BEAMS, WHERE SIGNIFICANT CORROSION IS OBSERVED.

A NEW PLATE AND BOLT HOOK ARE PROPOSED TO BE INSTALLED TO STRENGTHEN THE EXISTING STRUCTURE.



PROPOSED GANTRY WORK - NORTH COLUMNS NORTHER FACE
SCALE 1: 100

