




Key:-

VB Valley Beam

█ Defrass decay from beam (Subject to SE ) and treat with Wykamol 10.1 fungicide gel

█ Renew beam full length using C24 treated Douglas fir

▭ Steel flitch repair as per WML specifications and drawing

▭ Cut out decay and splice new section of wood to beam

Valley Beam report Gridlines B-D

New Warehouse SIM Liverpool Road Manchester

Ref WS/22702/SIM/24-11-2024