

Condition Report

652 CHORLTON LIBRARY ROOF LIGHT

SUBCONTRACTOR: Calibre Metalwork Limited
Hazel Knoll Farm
Torkington Road
Hazel Grove
Stockport
SK7 6NW
T: 0161 427 4603

The following report looked at the condition of the Glazing
bars

Identified as follows

1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16-17

IMAGE	Bar	NUMBER OF REPAIRS	DESCRIPTION OF REPAIRS	TOTAL
 	1	0	N/A	0
 	2	0	N/A	0

Calibre Metalwork Limited

		3	0	N/A	0
		4	1	Corrosion / Repair required	1
		5	1	Corrosion / Repair required	1
		6	0	N/A	0
		7	0	N/A	0
		8	0	N/A	0

Calibre Metalwork Limited

	9	0	N/A	0
	10	0	N/A	0
	11	0	N/A	0
	12	0	N/A	0
	13	0	N/A	0
	14	0	N/A	0
	15	0	N/A	0

Calibre Metalwork Limited

	16	0	N/A	0
	17	48	Copper inserts for all glazing bars need replacing. 48 off required	48

