



NOTES

- No dimensions to be scaled from this drawing.
- All dimensions to be checked on site.
- The designer must be notified where any discrepancy occurs between specification and drawing.
- COPYRIGHT: The contents of this drawing may not be reproduced in whole or part without the written permission of Paye Stonework & Restoration Ltd.

Sheet Size – A1

KEY

- Viewpoint
- Fractures
- Hairline fractures
- PIN** Recommend stainless steel pin repair (subject to structural engineers recommendation)
- DSP** Displaced stone
- FR** Friable stone. Recommend de-frassing stone to remove all loose material.
- Damaged stone (notable erosion, sections spalled). Recommend de-frass / indent repair / replacement unit.
- Existing render coat. Recommend tap testing to confirm well bonded.
- Redundant scaffold tie.
- FX** Street furniture (e.g. CCTV, alarm etc.).
- Staining to masonry
- No access (excluded from the survey)

REVISIONS

Architect	TBC
Engineer	HTS Engineers
Contract	Facade Survey, Sunlight House, Manchester, M3 3HP (24008)
Drawing Title	Facade Condition Survey - Little Quay Street Elevation (East)
Date	10/03/2024
Scale	NTS
Drawn by	TH
Chk'd By	
Drawing No.	24008-PAYE-DR-002 rev P02

PAYE
Stonework & Restoration
Stationmasters House, Mottingham Station Approach,
London, SE9 4EL
Website: www.payestone.co.uk Email: info@payestone.co.uk
tel: 020 8857 9111