

Form detail

Form detail report



Created on	Jul 8, 2022, 9:16 AM BST
Created by	John Carroll
Total items	3
Sorted by	Form date (Descending)
Filtered by	Custom selection

Contents

#169: Manhole / Chamber Inspection Checklist 3

#140: Manhole / Chamber Inspection Checklist 8

#126: Manhole / Chamber Inspection Checklist 16

Form detail

#169: Manhole / Chamber Inspection Checklist



Form details

Location	
Form date	Jun 17, 2022
Description	****SWO1
Submitted by	John Carroll
Status	Submitted
Last update	Jun 21, 2022, 1:57 PM BST
Last updated by	John Carroll
Included references	Assets Documents Form details Issues Photos

1. Manhole / Chamber Inspection Checklist

- 1.1 Project Name
Mal
- 1.2 Date
Jun 13, 2022
- 1.3 Location / Area / GL Ref
External drainage
- 1.4 Specification / Drawing References
DR01 revC3
- 1.5 MH / Chamber Reference
SW01 CATCHPIT
- 1.6 Chamber Type: Foul Water / Storm Water / Combined
STORM WATER

1.7 Chamber Entry Type: Step Irons / Ladder / PPIC
Step

1.8 Channels installed as required

☐

Yes

☐

No

☒

N/A

1.9 Concrete surround installed around chamber as required / Widewall rings seals used

☐

Yes

☐

No

☒

N/A

1.10 Benching / floor complete and of an acceptable standard

☒

Yes

☐

No

☐

N/A

Photos (1)



[20220617_080637_photo](#)

Added on Jun 17, 2022, 2:25 PM BST

Added by John Carroll

1.11 All pipe entries sealed as required

☐

Yes

☐

No

☒

N/A

1.12 Safety chains correctly installed if required

☐

Yes

☐

No

☒

N/A

1.13 Raising Pieces / Correct courses of brickwork installed, clean & pointed to acceptable standard

☐

Yes

☒

No

☐

N/A

1.14 All ring joints been pointed correctly

☒

Yes

☐

No

☐

N/A

Photos (1)[20220617_080637_photo](#)**Added on** Jun 17, 2022, 2:25 PM BST**Added by** John Carroll

1.15 Chamber free from leaks

☒

Yes

☐

No

☐

N/A

1.16 Chamber clean & free of debris

☒

Yes

☐

No

☐

N/A

Photos (1)



[20220620_091722_photo](#)

Added on Jun 21, 2022, 11:11 AM BST

Added by John Carroll

1.17 Correct cover class and depth installed correctly



Yes



No



N/A

Photos (2)



[20220620_091130_photo](#)

Added on Jun 21, 2022, 11:11 AM BST

Added by John Carroll



[20220526_132742_photo](#)

Added on May 27, 2022, 10:26 AM BST

Added by John Carroll

1.18 HOLD POINT: Final Inspection completed by Client and Signed off



Yes



No



N/A


Photos (2)



[20220621_133558_photo](#)

Added on Jun 21, 2022, 1:37 PM BST

Added by John Carroll



[20220621_112809_photo](#)

Added on Jun 21, 2022, 11:28 AM BST

Added by John Carroll

- 1.19 HOLD POINT: Final Inspection completed by Client and Signed off (Insert Name)
Kate Miller

HOLD POINT: Final Inspection completed by Client and Signed off (Insert Signature)

K Miller

Name	Date
Kate miller	June 21, 2022

Form detail

#140: Manhole / Chamber Inspection Checklist



Form details

Location	
Form date	Jun 1, 2022
Description	****FW01 combined
Submitted by	John Carroll
Status	Submitted
Last update	Jul 8, 2022, 8:57 AM BST
Last updated by	John Carroll
Included references	Assets Documents Form details Issues Photos

1. Manhole / Chamber Inspection Checklist

- 1.1 Project Name
Mal drainage
- 1.2 Date
May 1, 2022
- 1.3 Location / Area / GL Ref
External drainage
- 1.4 Specification / Drawing References
DR01 Rev c03
- 1.5 MH / Chamber Reference
FW01 / combined
- 1.6 Chamber Type: Foul Water / Storm Water / Combined

Combined

1.7 Chamber Entry Type: Step Irons / Ladder / PPIC
Steps

1.8 Channels installed as required



Yes



No



N/A

Photos (1)

[20220531_161128_photo](#)

Added on Jun 1, 2022, 11:05 AM BST

Added by John Carroll

1.9 Concrete surround installed around chamber as required / Widewall rings seals used



Yes



No



N/A

1.10 Benching / floor complete and of an acceptable standard



Yes



No



N/A

Photos (1)



[20220620_091722_photo](#)

Added on Jun 21, 2022, 11:11 AM BST

Added by John Carroll

1.11 All pipe entries sealed as required



Yes



No



N/A

Photos (1)



[20220620_091722_photo](#)

Added on Jun 21, 2022, 11:11 AM BST

Added by John Carroll

1.12 Safety chains correctly installed if required



Yes



No



N/A

1.13 Raising Pieces / Correct courses of brickwork installed, clean & pointed to acceptable standard

☐ Yes ☐ No ☒ N/A

1.14 All ring joints been pointed correctly

☒ Yes ☐ No ☐ N/A

Photos (1)



[20220620_091722_photo](#)

Added on Jun 21, 2022, 11:11 AM BST

Added by John Carroll

1.15 Chamber free from leaks

☒ Yes ☐ No ☐ N/A

Photos (1)



[20220620_091722_photo](#)

Added on Jun 21, 2022, 11:11 AM BST

Added by John Carroll

1.16 Chamber clean & free of debris



Yes



No



N/A

Photos (1)



[20220620_091722_photo](#)

Added on Jun 21, 2022, 11:11 AM BST

Added by John Carroll

1.17 Correct cover class and depth installed correctly



Yes



No



N/A

Photos (1)



[20220601_115532_photo_edited](#)

Added on Jun 1, 2022, 1:06 PM BST

Added by John Carroll

1.18 HOLD POINT: Final Inspection completed by Client and Signed off



Yes




No



N/A

Photos (8)



[20220617_080625_photo](#)

Added on Jun 17, 2022, 2:25 PM BST

Added by John Carroll



[20220601_115532_photo_edited](#)

Added on Jun 1, 2022, 1:06 PM BST

Added by John Carroll



[20220601_114825_photo](#)

Added on Jun 1, 2022, 1:06 PM BST


Added by John Carroll



[20220531_161920_photo](#)

Added on May 31, 2022, 4:21 PM BST

Added by Raj de Fonseca



[20220531_161128_photo](#)

Added on Jun 1, 2022, 11:05 AM BST


Added by John Carroll



[20220531_115657_photo](#)

Added on May 31, 2022, 12:14 PM BST

Added by John Carroll

[20220531_114252_photo](#)

Added on May 31, 2022, 12:14 PM BST

Added by John Carroll

[20220530_141257_photo](#)

Added on May 30, 2022, 3:45 PM BST

Added by John Carroll

- 1.19 HOLD POINT: Final Inspection completed by Client and Signed off (Insert Name)
Kate Miller

HOLD POINT: Final Inspection completed by Client and Signed off (Insert Signature)

Name	Date
Kate Miller	June 21, 2022

Form detail

#126: Manhole / Chamber Inspection Checklist




Form details

Location	
Form date	May 25, 2022
Description	Attenuation tank
Submitted by	John Carroll
Status	Submitted
Last update	May 27, 2022, 10:40 AM BST
Last updated by	John Carroll
Included references	Assets Documents Form details Issues Photos

1. Manhole / Chamber Inspection Checklist


- 1.1 Project Name
MAL external drainage
 - 1.2 Date
May 24, 2022
 - 1.3 Location / Area / GL Ref
Att tank surface water external line
 - 1.4 Specification / Drawing References
DR01- Rev C03
- Photos (2)**



20220525_131621_photo

Added on May 25, 2022, 1:16 PM BST

Added by John Carroll



20220525_131601_photo

Added on May 25, 2022, 1:28 PM BST

Added by John Carroll

1.5 MH / Chamber Reference
Att 1

1.6 Chamber Type: Foul Water / Storm Water / Combined
Storm water

1.7 Chamber Entry Type: Step Irons / Ladder / PPIC
Na

1.8 Channels installed as required



Yes



No



N/A

1.9 Concrete surround installed around chamber as required / Widewall rings seals used



Yes



No



N/A

1.10 Benching / floor complete and of an acceptable standard



Yes



No



N/A

1.11 All pipe entries sealed as required



Yes



No



N/A

1.12 Safety chains correctly installed if required

☐ Yes ☐ No ☒ N/A

1.13 Raising Pieces / Correct courses of brickwork installed, clean & pointed to acceptable standard

☐ Yes ☐ No ☒ N/A

1.14 All ring joints been pointed correctly

☐ Yes ☐ No ☒ N/A

1.15 Chamber free from leaks

☐ Yes ☐ No ☒ N/A

1.16 Chamber clean & free of debris

☒ Yes ☐ No ☐ N/A

Photos (2)



[20220525_133210_photo](#)

Added on May 25, 2022, 2:33 PM BST

Added by John Carroll



[20220525_133150_photo](#)

Added on May 25, 2022, 2:33 PM BST

Added by John Carroll

1.17 Correct cover class and depth installed correctly

☒ Yes ☐ No ☐ N/A

Photos (1)



[20220525_133134_photo](#)

Added on May 25, 2022, 2:32 PM BST

Added by John Carroll

1.18 HOLD POINT: Final Inspection completed by Client and Signed off



Yes



No



N/A

Photos (2)



[20220525_133134_photo](#)

Added on May 25, 2022, 2:32 PM BST

Added by John Carroll



[20220525_133134_photo](#)

Added on May 25, 2022, 2:32 PM BST

Added by John Carroll

1.19 HOLD POINT: Final Inspection completed by Client and Signed off (Insert Name)

Kate Miller

HOLD POINT: Final Inspection completed by Client and Signed off (Insert Signature)



Name	Date
John Carroll	May 27, 2022