



Damaged window head with exposed rebar and missing render



Missing render and frost damaged brickwork



Damaged render and hopper not fixed to wall



Damaged window head and render, missing grout at cornice



Cracked internal lintel with exposed rebar



Typical frost damaged cast stone to window surround



Damaged window head and outer lintel, damaged and missing render



Damaged cast stone to window jamb