

Window Schedule - North				
Mark	Height (mm)	Width (mm)	Required	Description
Level 00				
00-012	1500	1280		Blinds
00-013A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Window actuators to be repaired / Blinds
00-013B	1950	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
00-014A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Window actuators to be repaired / Blinds
00-014B	1950	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
00-015A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Window actuators to be repaired / Blinds
00-015B	1950	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
00-016A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Window actuators to be repaired / Blinds
00-016B	1950	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
00-017A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Window actuators to be repaired / Blinds
00-017B	1950	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
00-018A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Window actuators to be repaired / Blinds
00-018B	1950	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
00-019A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Window actuators to be repaired / Blinds



1 Proposed Glazing Window Alterations_North Elevation

1 : 100

Window Schedule - North				
Mark	Height (mm)	Width (mm)	Required	Description
00-019B	1950	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
Level 01				
01-012A	950	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
01-012B	1500	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
01-012C	950	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
01-012D	1500	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
01-012E	950	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
01-012F	1500	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
01-013A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Window actuators to be repaired / Blinds
01-013B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
01-014A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Window actuators to be repaired / Blinds
01-014B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
01-015A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Window actuators to be repaired / Blinds
01-015B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
01-016A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Window actuators to be repaired / Blinds
01-016B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
01-017A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Window actuators to be repaired / Blinds
01-017B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
01-018A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Window actuators to be repaired / Blinds
01-018B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
Level 02				
02-012A	950	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
02-012B	1500	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
02-012C	950	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
02-012D	1500	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
02-012E	950	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
02-012F	1500	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
02-013	1810	1020	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
02-014	1810	1020	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
02-015	1810	1020	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
02-016	1810	1020	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
02-017	1810	1020	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
02-018	1810	823	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
02-019	1810	823	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
Level 03				
03-002A	950	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
03-002B	1500	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
03-002C	950	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
03-002D	1500	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
03-002E	950	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	
03-002F	1500	917	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	

All replacement external glazing to be Fineso Heritage - Traditional Light - 13mm as product data sheet installed to manufacturer's recommendations.

Frames to have painted rebated beads externally and internally, new Fineso Heritage Glazing + airtightness system to frame perimeter

New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec - **fixed sashes**

Please refer to drawing 3216-RBUM-ARC-XX-ZZ-SHA-3216 for details of replacement casements and airtightness system



Notes

- This drawing is copyright
- Do not scale dimensions from this drawing
- This drawing is to be read in conjunction with all other relevant drawings
- All dimensions on this drawing are to be supplied to the architect
- Do not modify any element of this drawing
- Use drawings only for proposed layout
- This drawing may contain colour

Scale Bar

0 1m 2m 3m 4m

Scale 1:100

North Point

DRAFT

The following external model files are included within this drawing

C1	2024/08/21	Remaining windows and details issued for Construction	AB	RM
P12	2024/08/07	Windows connected to letter of comfort	AB	RM
P11	2024/08/07	Window Schedules updated	AB	RM
P10	2024/08/15	Change Control 03.04.05	AB	RM
P9	2024/04/26	UIC comments	AB	RM
P8	2024/03/21	Wall heights adjusted in wellbeing and acc show; window description added	AB	RM
P7	2024/01/16	Windows on south elevation added to schedule	AB	RM
P6	2023/12/15	Fire Stopping details issued to Building Control and Fire Engineer	AB	RM
P5	2023/10/01	Listed Building Consent Submission	AB	RM
P4	2023/09/06	Stage 4 Issue for Costing	AB	RM
P3	2023/08/04	Drawings issued for LBC Application	AB	RM
P2	2023/07/01	Preliminary Issue to Heritage Consultant	AB	RM
P1	2023/06/02	Stage 1 Preliminary Issue for costing	AB	RM
Rev	Date	Revision Notes	Drawn	Review

MANCHESTER

The University of Manchester

ARCADIS

Project

Rutherford Building

Drawing File

Window + External Door Schedule_North Elevation

Job Number	Date	Security Classification	Drawn By
141532	FEB23		MTW
Scale/As	Purpose	Reviewed By	
As indicated	CONSTRUCTION	RM	
Drawing Number	Revision		
3213-RBUM-ARC-XX-ZZ-SHA-3213	C1		