


111 DEANS_GATE M3 2BQ - photographic audit in support of LBC application

	
1 - Detail of RHS original cornice abutting recent plasterboard ceiling	2 - Existing high level mesh panels to be retained - cornice / plasterboard ceiling abutment to RHS
	
2 - Detail of rear wall original cornice abutting recent plasterboard ceiling	4 - existing fixings into non-original plasterboard ceiling
	
5 - NE corner high level curved column above recent boxing out	6 - NE corner showing original cornice and recent plasterboard infill - note edge of exposed plasterboard

111 DEANS_GATE M3 2BQ - photographic audit in support of LBC application




7 - Non- original boxing out to be removed



8 - non-original high level joinery / wall lining to be removed




9 - free standing / non original door frame / partition to be removed



10 - non original high level joinery and column to rear wall / wall lining to be removed



11 - non original column and wall lining to be removed -vault gate to be retained



12 - non-original high level bulkhead to be removed; note white wall lining behind tiling is to be retained (non-original)