

Appendix: Photographs



East Wing to Hough Hall Road



South Front



The rear is in a state of collapse.



North gable. Panels are detaching.



The timber frame is evident within the west wing.



Much of the framing has been lost in the main body of the house.