


Victoria Baths

Friday, 06 October 2023

Prepared For Performance Electrical


18 Issues Identified





Main Entrance

Call point



Front Entrance Door

Call point



Front Entrance

Typical panel




Front Entrance


Typical positioning of panel




Existing Equipment
Existing call point and fire alarm panel



Internal Wooden Panel
Call point on wooden entrance doors



Tiled Area
Call point at rear building




Tiled Area
Close up image of call point




Rear of Building

Call point near exit on tiled surface




Exit To Rear

Call point adjacent to rear exit



Outbuilding

Call point in outbuilding



Outbuilding Image 2

Call point I outbuilding image 2



First Floor

Call in living area entrance




First Floor

Call point in corridor



Left Hand Side Front Door

Call point at side of door in office area



New Panel Location



New Panel Location Image 2