


Maryland – Southern Elevation Window Schedule



Maryland – Eastern Elevation Window Schedule



Maryland – Northern Elevation Window Schedule



Maryland – Western Elevation 1 Window Schedule




Maryland – Western Elevation 2 Window Schedule



Window Reference	Room	Image(s)			Refurbishment / Repair		
G'1 & G'2	MRG1				   		
G'3	MRG1	 			 		
G'4, G'5, G'6	MRG1						
							

G'7	MRG1		
G'8, G'9, G'10	MRG2		
G'11, G'12, G'13	MRG9		

G'14	Corridor		Work yet to be undertaken
G'15	MRG3		Work yet to be undertaken
G'16, G'17, G'18	MRG4		Work yet to be undertaken

G'19, G'20, G21	MRG4		Work yet to be undertaken
G'22		 	 
G'23			 

G'24		 	 
G'25			

G'26



G'27



G'28

Kitchen



G'29	Kitchen Annex		 
1'1	MR16	 	 

1'2	MR16	 	 
1'3	MR16		 

1'4	MR16		 
1'5	Corridor		

1'6	MR15	A vertical window with a dark frame. A light-colored roller blind is partially open, revealing a view of a green lawn, trees, and a brick building in the background. A close-up view of the window frame and the bottom edge of the blind, showing the green lawn and trees outside.	A vertical window with a dark frame and an arched top. The view shows a green lawn, trees, and a brick building in the background, with a cloudy sky visible through the arched top. A close-up view of the window frame and the bottom edge of the blind, showing the green lawn and trees outside.
1'7	MR15	A vertical window with a dark frame and an arched top. The view shows a green lawn, trees, and a brick building in the background, with a cloudy sky visible through the arched top. A close-up view of the window frame and the bottom edge of the blind, showing the green lawn and trees outside.	A vertical window with a dark frame and an arched top. The view shows a green lawn, trees, and a brick building in the background, with a cloudy sky visible through the arched top. A close-up view of the window frame and the bottom edge of the blind, showing the green lawn and trees outside.

1'8	Corridor	 A photograph of a window in a corridor. The window is white-framed and looks out onto a green lawn, trees, and a red brick building under a cloudy sky.	 A photograph of a window in a corridor. The window is white-framed and looks out onto a brick wall and a small white structure.
1'9	MR14	 A photograph of a window in a room. The window is white-framed and looks out onto a green lawn, trees, and a red brick building under a blue sky with white clouds.	  A photograph of a window in a room. The window is white-framed and looks out onto a green lawn, trees, and a red brick building under a blue sky with white clouds. Below the main image is a close-up photograph of the window frame, showing the white paint and the wooden structure.


1'10	MR14		 
1'11	MR13		 

1'12

MR12



1'13	MR12		 
1'14	MR12		 

1'15 & 1'16	MR11		 
----------------------------	-------------	---	---

1'17	MR112		
1'18	MR112		

1'19	MR112		 
1'20	MR112	 	 

1'21	MR112	 	 
1'22	Female Toilet	 	 

1'23	Single Toilet		 
1'24	MR19		 

1'25

MR19



1'26	MR19	 	 
1'27	Landing		 

1'28	Landing	A photograph of a window looking out onto a stone building with a chimney. The window frame is white. A close-up photograph of the white window frame and sill, showing the window handle.	A photograph of a window looking out onto a stone building with a chimney. The window frame is white. A close-up photograph of the white window frame and sill, showing the window handle.
1'29	Landing	A photograph of a window looking out onto a stone building with a chimney. The window frame is white. A close-up photograph of the white window frame and sill, showing the window handle.	A photograph of a window looking out onto a stone building with a chimney. The window frame is white. A close-up photograph of the white window frame and sill, showing the window handle.