

Window Schedule - South				
Mark	Height (mm)	Width (mm)	Required	Description

Level 00				
00-022A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
00-022B	1670	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
00-023A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
00-023B	1670	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
00-024A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
00-024B	1670	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
00-025A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
00-025B	1670	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
00-026A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
00-026B	1670	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
00-027A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
00-027B	1670	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
00-028A	983	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
00-028B	1670	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds

Level 01				
01-020A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
01-020B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
01-021A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
01-021B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
01-022A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
01-022B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds

Window Schedule - South				
Mark	Height (mm)	Width (mm)	Required	Description
01-023A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
01-023B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
01-024A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
01-024B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
01-025A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
01-025B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
01-026A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
01-026B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds
01-027A	1273	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Electrical Window Actuators required / Blinds
01-027B	2035	1035	New timber casements to match existing, Glazing replaced with vacuum glazed system, frames refurbished weather seals installed and air tightness system applied as spec	Blinds



1 Proposed Glazing Window Alterations_South Elevation
1 : 100

Notes:

- This drawing is copyright.
- Do not scale dimensions from this drawing.
- This drawing is to be read in conjunction with all other relevant drawings.
- All discrepancies on this drawing are to be reported to the architect.
- Do not modify any element of this drawing.
- Use drawing only for purpose(s) issued.
- This drawing may contain colour.

Scale Bar

0

1m

3m

5m

Scale: 1:100

North Point

Key Plan

The following external model files are included within this drawing:

P6

2023/12/01

Listed Building Consent Submission.

AB

RM

P5

2023/11/24

Stage 4 Issue for Costing

MC

RM

P4

2023/10/06

Stage 4 Issue for Costing

AB

RM

P3

2023/08/04

Drawings issued for LBC Application

AB

RM

P2

2023/07/21

Preliminary Issue to Heritage Consultant

AB

RM

P1

2023/06/02

Stage 3 Preliminary Issue for costing

AB

RM

Rev

Date

Revision Notes

Drawn

Review

MANCHESTER

1824

The University of Manchester

ARCADIS

Project

Rutherford Building

Drawing Title

Window + External Door Schedule_South Elevation

Job Number

141532

Date

FEB'23

Security Classification

Drawn By

MTW

Scale@A1

1 : 100

Purpose

LISTED BUILDING CONSENT

Reviewed By

RM

Drawing Number

3212-RBUM-ARC-XX-ZZ-SH-A-3212

Revision

P6