





2



5



-  Existing construction
-  Existing high level pipes
-  Existing high level ducts
-  Existing structure
- New 60 minute fire rated fabric