



Photo 1: St James Church boundary/retaining wall on Stenner Lane, visible cracking and bulging of wall



Photo 2: Holes and missing mortar formed in retaining wall between stone wall sections caused by movement.



Photo 3: Cedar tree in St James's Church grounds approx. 1 metre from boundary wall. Photograph taken from Stenner Lane.



Photo 4: Cedar tree in St James's Church grounds photograph taken from inside church grounds.



Photo 5: Boundary wall with missing stone and visible movement of stones, Photo taken in August 2022.



Photo 6: Boundary wall showing areas of previous wall repairs and stone replacement on Stenner Lane.



Photo 7: Historic wall repairs/replacement, new stones installed to top course of wall on Stenner Lane.



Photo 8: 4 [Nr] Gabion baskets installed adjacent boundary wall in October 2022.



Photo 9: Gabion baskets with temporary fencing around. Photograph taken in October 2022.



Photo 10: Existing cast iron railings fixed to coping stones on boundary wall at St James's Church/Stenner Lane.



Photo 11: Existing cast iron railings fixed to coping stones on boundary wall at St James's Church/Stenner Lane.