

ROOM F.13

- No cornice
- Plasterboard ceiling
- Partially collapsed ceiling as noted on the plan
- Ceiling is damaged in various areas



ROOM F.14

- No cornice
- Plasterboard ceiling
- Half of the ceiling has collapsed revealing floor joists and the floor above
- Ceiling is severely damaged



ROOM F.15

- No cornice
- Half of the ceiling has collapsed



ROOM F.16

- No cornice
- Partially collapsed ceiling as noted on the plan
- Ceiling is damaged in various areas
- Bad water damage to ceiling



ROOM F.17

- No cornice
- Partially collapsed ceiling as noted on the plan
- Ceiling is damaged in various areas
- Bad water damage to ceiling

