


ROOM F.18

- Cornice as noted on the plan
- Water damage to cornice
- Plasterboard ceiling
- Signs of water damage to ceiling



ROOM F.20

- No cornice
- Plasterboard ceiling
- Early signs of water damage to ceiling



existing lathe and plaster ceiling
to be underboarded
[with 2 layers of fire board]
existing cornice to be retained
repaired as necessary
[where cornice is missing
remold will take place]



ROOM F.19

- Limited areas of surviving cornice as noted on the plan
- There is some damage to the cornice
- All ceiling is plasterboard

