


GROUND FLOOR | WINDOWS



Do not scale from this drawing.
All dimensions are to be checked on site prior to commencing works on site. Discrepancy found between information given on this drawing and that given elsewhere or recorded on site shall be notified immediately to the project architect in writing.

PLANNING ISSUE



snookarchitects		project:	rev.	date	description
89 Wood Street	Liverpool	bridgewater house			
L1 4NU		dwg no:		140	
t: 0151 707 0100		dwg title:		window survey [1 of 16]	
		scale:		1:100 @ a1	

WINDOW WG.01

- Unable to open
- Single glazing
- Modern glass
- Broken glass
- Non original frame (damaged)




WINDOW WG.02

- Unable to open
- Single glazing
- Modern glass
- Non original frame (probably)
- Damaged frame




WINDOW WG.03

- Unable to open
- No glass
- Non original frame



WINDOW WG.04

- Unable to open
- No glass
- Non original frame (probably)
- Damaged frame



Do not scale from this drawing.
All dimensions are to be checked on site prior to commencing works on site. Discrepancy found between information given on this drawing and that given elsewhere or recorded on site shall be notified immediately to the project architect in writing.


PLANNING ISSUE



snookarchitects	project:	bridgewater house	rev.	date	description
89 Wood Street					
Liverpool					
L1 4NU	dwg no:	141			
t: 0151 707 0100	dwg title:	window survey [2 of 16]			
	scale:	1:100 @ A1			

WINDOW **WG.05**

- Unable to open
- No glass
- Damaged frame
- Non original frame (probably)



WINDOW **WG.09**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks damaged
- Glass looks broken



WINDOW **WG.15**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks damaged
- Glass looks broken




WINDOW **WG.16**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks damaged
- Glass looks broken



WINDOW **WG.17**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks damaged
- Glass looks broken



WINDOW **WG.18**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks damaged
- Glass looks broken



WINDOW **WG.19**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks damaged
- Glass looks broken



WINDOW **WG.20**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks damaged
- Glass looks broken




WINDOW **WG.21**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks damaged
- Glass looks broken




WINDOW **WG.22**

- Unable to open
- Original frame
- Damaged frame
- Glass mostly broken





WINDOW WG.24

- Unable to open
- Original frame
- Damaged frame
- No glass (mostly broken)
- Non original glass



WINDOW WG.25

- Unable to open
- Original frame
- Damaged frame
- No glass (mostly broken)
- Non original glass



WINDOW WG.26

- Unable to open
- Original frame
- Damaged frame
- No glass (mostly broken)
- Non original glass



Do not scale from this drawing.
All dimensions are to be checked on site prior to commencing works on site. Discrepancy found between information given on this drawing and that given elsewhere or recorded on site shall be notified immediately to the project architect in writing.

PLANNING ISSUE



rev.	date	description
1	144	144
2	144	144
3	144	144
4	144	144
5	144	144
6	144	144
7	144	144
8	144	144
9	144	144
10	144	144
11	144	144
12	144	144
13	144	144
14	144	144
15	144	144
16	144	144
17	144	144
18	144	144
19	144	144
20	144	144
21	144	144
22	144	144
23	144	144
24	144	144
25	144	144
26	144	144
27	144	144
28	144	144
29	144	144
30	144	144
31	144	144
32	144	144
33	144	144
34	144	144
35	144	144
36	144	144
37	144	144
38	144	144
39	144	144
40	144	144
41	144	144
42	144	144
43	144	144
44	144	144
45	144	144
46	144	144
47	144	144
48	144	144
49	144	144
50	144	144
51	144	144
52	144	144
53	144	144
54	144	144
55	144	144
56	144	144
57	144	144
58	144	144
59	144	144
60	144	144
61	144	144
62	144	144
63	144	144
64	144	144
65	144	144
66	144	144
67	144	144
68	144	144
69	144	144
70	144	144
71	144	144
72	144	144
73	144	144
74	144	144
75	144	144
76	144	144
77	144	144
78	144	144
79	144	144
80	144	144
81	144	144
82	144	144
83	144	144
84	144	144
85	144	144
86	144	144
87	144	144
88	144	144
89	144	144
90	144	144
91	144	144
92	144	144
93	144	144
94	144	144
95	144	144
96	144	144
97	144	144
98	144	144
99	144	144
100	144	144



WINDOW WG.27

- Unable to open
- Original frame
- Damaged frame
- No glass (mostly broken)
- Non original glass



WINDOW WG.28

- Unable to open
- Original frame
- Damaged frame
- No glass (mostly broken)
- Non original glass



WINDOW WG.29

- Unable to open
- Original frame
- Damaged frame
- No glass (mostly broken)
- Non original glass



Do not scale from this drawing.
All dimensions are to be checked on site prior to commencing works on site. Discrepancy found between information given on this drawing and that given elsewhere or recorded on site shall be notified immediately to the project architect in writing.

PLANNING ISSUE



snookarchitects	project:	bridgewater house
89 Wood Street	dwg no:	145
Liverpool	dwg title:	window survey [6 of 16]
L1 4NU	scale:	1:100 @ a1
t: 0151 707 0100		



WINDOW WG.30

- Unable to open
- Original frame
- Damaged frame
- No glass (mostly broken)
- Non original glass



WINDOW WG.31

- Unable to open
- Original frame
- Damaged frame
- No glass (mostly broken)
- Non original glass



WINDOW WG.32

- Unable to open
- Original frame
- Damaged frame
- No glass (mostly broken)
- Non original glass



Do not scale from this drawing.
All dimensions are to be checked on site prior to commencing works on site. Discrepancy found between information given on this drawing and that given elsewhere or recorded on site shall be notified immediately to the project architect in writing.


PLANNING ISSUE



snookarchitects	project:	bridgewater house
89 Wood Street	dwg no:	146
Liverpool	dwg title:	window survey [7 of 16]
L1 4NU	scale:	1:100 @ a1
t: 0151 707 0100		


WINDOW **WG.33**

- Unable to open
- Original frame
- Damaged frame
- No glass (mostly broken)
- Non original glass




WINDOW **WG.34**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks badly damaged




WINDOW **WG.39**

- Unable to open
- Original frame
- Damaged frame
- Non original glass



FIRST FLOOR | WINDOWS



Do not scale from this drawing.
All dimensions are to be checked on site prior to commencing works on site. Discrepancy found between information given on this drawing and that given elsewhere or recorded on site shall be notified immediately to the project architect in writing.

PLANNING ISSUE



snookarchitects	project:	date	description
89 Wood Street Liverpool L1 4NU t: 0151 707 0100	bridgewater house	148	
	dwg no:		
	dwg title:	window survey [9 of 16]	
	scale:	1:100 @ a1	


WINDOW W1.01

- Unable to open
- Damaged frame
- Non original glass
- Broken glass



WINDOW W1.02

- Unable to open
- Non original frame
- Non original glass



WINDOW W1.03

- Unable to open
- Non original frame
- Frame badly damaged
- Non original glass
- Glass broken



Do not scale from this drawing.
All dimensions are to be checked on site prior to commencing works on site. Discrepancy found between information given on this drawing and that given elsewhere or recorded on site shall be notified immediately to the project architect in writing.

PLANNING ISSUE



WINDOW **W1.04**

- Unable to open
- Non original frame
- Frame badly damaged
- Non original glass
- Glass broken



WINDOW **W1.05**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks badly damaged



WINDOW **W1.06**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks badly damaged




WINDOW **W1.07**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Window is completely destroyed



WINDOW **W1.08**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame is completely destroyed
- There seems to be no glass remaining
- Window is boarded from the outside



WINDOW **W1.13**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks badly damaged



WINDOW **W1.14**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks badly damaged
- Glass appears to be broken



WINDOW **W1.15**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks badly damaged
- Glass appears to be broken



WINDOW **W1.16**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks badly damaged
- Window is partially boarded up



WINDOW **W1.17**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks badly damaged
- Window is partially boarded up



WINDOW **W1.18**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame appears to be gone completely
- No glass remaining
- Window is boarded from the outside



WINDOW **W1.19**

- Restricted access - Window is inaccessible due to collapsed ceiling and/or unsafe floor structure
- Photo taken from a distance
- Frame looks badly damaged and partially boarded up
- Glass is missing and/or broken



WINDOW **W1.20**

- Frame looks original
- Frame is rotten
- Glass is missing and/or broken




WINDOW **W1.22**

- Unable to open
- Original frame
- Frame is rotten
- Glass is missing and/or broken
- No chords



WINDOW **W1.23**

- Unable to open
- Original frame
- Frame is rotten
- Glass is missing and/or broken
- No chords




WINDOW W1.24

- Unable to open
- Original frame
- Frame is rotten
- Glass is missing and/or broken
- No chords



WINDOW W1.25

- Unable to open
- Original frame
- Frame is rotten and damaged
- Non original glass
- No chords



WINDOW W1.26

- Unable to open
- Original frame
- Frame is rotten and damaged
- Non original glass
- Glass is missing and/or broken
- No chords



Do not scale from this drawing.
All dimensions are to be checked on site prior to commencing works on site. Discrepancy found between information given on this drawing and that given elsewhere or recorded on site shall be notified immediately to the project architect in writing.

PLANNING ISSUE




snookarchitects
89 Wood Street
Liverpool
L1 4NU
t: 0151 707 0100

project: **bridgewater house**
dwg no: **153**
dwg title: **window survey [14 of 16]**
scale: **1:100 @ a1**

rev. date description

WINDOW W1.27

- Unable to open
- Unable to assess it properly - window is boarded up
- Frame looks original
- Frame is damaged
- Non original glass
- Glass missing and/or broken
- No chords



WINDOW W1.28

- Unable to open
- Original frame
- Non original glass
- Most of the glass is missing
- Chords snapped



WINDOW W1.29

- Unable to open
- Original frame
- Non original glass
- Glass is missing and/or broken



Do not scale from this drawing.
All dimensions are to be checked on site prior to commencing works on site. Discrepancy found between information given on this drawing and that given elsewhere or recorded on site shall be notified immediately to the project architect in writing.

PLANNING ISSUE




WINDOW W1.30

- Unable to open
- Original frame
- Non original glass
- Glass is smashed
- Chords are missing



WINDOW W1.31

- Unable to open
- Original frame
- Non original glass
- Glass is smashed
- Chords are missing



WINDOW W1.34

- Unable to open
- Window is partially boarded up
- Non original frame
- Frame is skewed
- Glass looks modern

