



Roof repairs necessary to the rose garden elevation



Displaced guttering requires repair



Rainwater goods blocked by Ivy



Location of new facility (behind door on the left)



Inside the new facility looking North.



Inside the new facility looking south.



Existing doors to rear



Existing sliding door wheel




Existing sliding door wheel bracket



Existing door runner




Existing stone flag floor



Plastic adjustable cradles and aluminium joists to sit on stone flags



VEVOR carbon steel door track



VEVOR carbon steel door hangers



Flush mounted LED ceiling light



Typical changing places facility