



PORTLAND STREET ELEVATION. (Image taken prior to current repair works.)



CHARLOTTE STREET AND REYNER STREET ELEVATIONS. (Image taken prior to current repair works)



Vegetation to be removed and masonry repointed to cornice. See spec for outline description of new lead cladding to cornice.



Water staining on the masonry at high level is to be investigated further.



Typical sash windows for redecoration.



Typical sash windows (previously repaired). Include allowance for easing works.



Spalled stone and masonry. (image taken prior to current works)



Typical indent repair to stone coursing.



Front door to be overhauled and redecorated.



Typical cast iron railing to be redecorated and indent repairs to mullions behind.