


Appendix III – Photosheets



Deansgate (east) elevation viewed from the north-east



Example of moss and algae growth to window sill and string course on Deansgate (east) elevation



Example of moss and algae growth on Spinningfields (south) elevation



Example of unsympathetic previous mortar repair to cracking on Spinningfields (south) elevation



Stonework damage to window BW49(S) on Spinningfields (south) elevation



Stonework damage to window GW52(S) on Spinningfields (south) elevation



Wood Street (north) elevation viewed from the north-west



Example of moss and algae growth on Wood Street (north) elevation



Example of moss and algae to buttress on Wood Street (north) elevation



Example of moss and algae growth and open joints on Wood Street (north) elevation