



Window 1 - Room 0/16 The Hall



Window 2 - Room 0/16 The Hall



Window 5 - Room 0/16 The Hall



Window 3 - Room 0/16 The Hall



Window 4 - Room 0/16 The Hall




East Door - Into Room 0/16 The Hall

- notes:
1. DO NOT SCALE FROM THIS DRAWING - USE FIGURED DIMENSIONS ONLY.
 2. TO BE READ IN CONJUNCTION WITH ALL OTHER CONSULTANTS / SPECIALISTS DRAWINGS. REPORT ANY DISCREPANCIES BEFORE AFFECTED WORK COMMENCES.
 3. ALL SETTING OUT DIMENSIONS TO BE CHECKED ON SITE BY CONTRACTOR BEFORE WORK COMMENCES.

FABRIC REPAIRS KEY

-  Repair several panes of glass and three sections of leaded lights. One section missing 50%, two sections local damage.
-  Splice in new timbers to the base of the timber frame.

KEY PLAN



CLIENT
PROJECT
TITLE
NUMBER
REVISION
STATUS
SCALE
DATE
DRAWN BY
CHECKED BY

Historic England
Baguley Hall
Historic Windows Photo Log
BGH-SEV-XX-ZZ-DR-A-3050
P01
PLANNING
1:100 @A3
02/08/22
SGi
LM

seven.
SEVENARCHITECTURE.CO.UK

Studios at :

Unit 1.3, Waulk Mill, 51 Bengal Street
MANCHESTER, M4 6LN
t : 0161 236 5655
Clarendon House, Victoria Avenue,
HARROGATE, HG1 1DY
t : 01423 709 807
24 Greville Street, **LONDON**,
EC1N 8SS
t : 0203 036 0691

REVISIONS | P01 ISSUED_FOR_COSTING 12/08/22 SGI LM
DATE; DRAWN; CHECK