



Photo 1: Photo taken on Stenner Lane facing the Eastern perimeter boundary retaining wall to Fletcher Moss Art Gallery.



Photo 2: Leaning boundary wall close to stone arch entrance on Stenner Lane.



Photo 3: Lime tree adjacent to the boundary wall. This section of wall was removed as part of the emergency works.



Photo 4: Photograph of cracking to boundary wall caused by tree growth and movement. Location of emergency works to reduce the wall height by 9 courses of brickwork, undertaken in June 2021. See Photo 5 for final finish.



Photo 5: Section of boundary wall removed as part of the emergency works.



Photo 6: Boarded up section of wall put in place to temporarily secure the grounds.



Photo 7: Existing section of wall to be dismantled and rebuilt to a reduced height to match attached lower section of boundary wall.



Photo 8: Missing Coping stones; the sandstone coping stones are missing to the majority of this section of wall on Stenner Lane



Photo No.9: See changes in wall thickness from top of boundary wall down to increased thickness at ground level.



Photo No.10: Highlighted sections of wall that need to be permanently removed to allow the trees space for future growth.



Photo No.11: Damage to section of boundary wall to Fletcher Moss Park to Western side of Stenner Lane.



Photo No.12: Stepped cracking to boundary wall on western side of Stenner Lane adjacent Fletcher Moss Park.