

Appendix A

A: Photographic Schedule



Photo 01 – Existing Front Elevation



Photo 02 – Typical Side Elevation



Photo 03 – Aerial Roof View



Photo 04 – Temporary Scaffold Roof to Rear Elevations

Appendix A



Photo 05 – Typical Section of Failed Render




Photo 06 – Typical Section of Failed Render



Photo 07 – Typical Cracking to External Render



Photo 08 – Typical Scaffold Fixing

Appendix A



Photo 09 – Kentledge Scaffold to Rear Elevation



Photo 10 – Temporary Roof Scaffold to Side Elevation



Photo 11 – Existing Roof Details



Photo 12 – Existing Gutter Details

Appendix A



Photo 13 – Existing Flat Roof Covering (FR1)




Photo 14 – Existing Projecting Eaves



Photo 15 – Dry Rot Outbreak (Grond Floor)



Photo 16 – Dry Rot Outbreak (Grond Floor)

Appendix A



Photo 17 – Failed Plaster due to Water Ingress (First Floor)



Photo 18 – Failed Plaster due to Water Ingress (First Floor)



Photo 19 – Failed Internal Linings due to Water Ingress (First Floor)



Photo 20 – Failed Internal Linings due to Water Ingress (First Floor)

Appendix A



Photo 21 – Existing Kitchenette (First Floor)



Photo 22 – Existing Kitchenette (First Floor)



Photo 23 – Failed Internal Linings due to Water Ingress (First Floor)



Photo 24 – Overboard to Lathe & Plaster Ceiling (Ground Floor)

Appendix A



Photo 25 – Typical Ceiling Articulation




Photo 26 – Typical Wall Articulation



Photo 27 – Failed Ceiling Lining (Basement)



Photo 28 – Existing Rooflight (Ground Floor)