

GAS MEMBRANE VALIDATION – BELLE VUE

Project Name: Belle Vue Stadium**Project Number:** 12-123**Client:** Countryside Properties**Date:** 30-10-2023**Project Manager & Qualifications:** N. Sellars – MSci (Hons), FGS, MEnvSc**E3P Engineer & Qualifications:** J. Newall – GGS Training**Gas Membrane Installer :** Chandos Civils**Ground Gas Risk Assessment:** Amber 1**Plots:** 214

OVERVIEW

The membrane comprised the Visqueen Ultimate HC Blok (Gold) resistant to radon, carbon dioxide, methane and VOCs. E3P can confirm there were no holes or rips at the inspection time.

E3P inspected all external joints, and E3P can confirm that the membrane was overlapped and double-taped. The membrane was taped using double-sided jointing tape. All the overlaps were then additionally taped using foil-backed girth tape.

Each unit has a service duct located at the front and outer edge of the property. E3P inspected each one and can confirm that the top hats have been adequately sealed against the membrane.

Based on the information provided within this report, the site inspections and validation checklists, E3P can confirm that Plot 214 has been installed with gas protection measures following Amber 1 to an acceptable level of workmanship.

A list of plots requiring validation and their associated validation letters is presented in Table 1.



Geo-Environmental



Acoustics

Remediation and
Enabling Earthworks
Design

Arboriculture

Compliance
& Due Diligence

Ecology



Industrial Permitting



Geotechnical

MEMBRANE SPECIFICATION: VISQUEEN GAS MEMBRANE (GOLD)

Technical Datasheet - Product Overview



Technical support: +44 (0) 333 202 6800
Date Published: 05/06/2023

Visqueen Ultimate HC BLOK

Features and benefits

- Agreement certified - third party accreditation
- Complies with CIRIA C748:2014 - Industry standard for volatile organic compounds (VOC) protection
- Complies with the methane gas transmission rate, mass per unit area and thickness requirements of BS 8485:2015 + A1:2019 - Industry standard for methane and carbon dioxide protection
- Flexible - easy to detail and install on site
- Multi functional - also acts as a radon and damp proof membrane
- Dual jointing methods - lap joints can be taped or heat welded

Product description

Visqueen Ultimate HC Blok is a 0.5mm thick, chemically resistant co-extruded volatile organic compound barrier and gas barrier. It is coloured gold on the upper surface and white on the reverse. The product is supplied in single wound rolls (not folded), 2.44m x 41m.

Approvals and standards

- Third party accreditation (BDA certificate BAF-18-051-P-A-UK)
- Complies with CIRIA C748:2014
- Complies with the methane gas transmission rate, mass per unit area and thickness requirements of BS 8485:2015 + A1:2019
- Suitable for all Characteristic Gas Situation (CS) ground gas regimes
- Conforms to the specification requirements of NHBC Amber 1 and Amber 2 applications
- Conforms to the specification requirements of BR 211:2015
- CE Mark EN 13967:2012
- Quality Management System ISO 9001:2015
- Occupational Health and Safety System ISO 45001:2018
- Environmental Management System ISO 14001:2015

Usage

Visqueen Ultimate HC Blok is suitable for use in all types of buildings to prevent the ingress of harmful levels of volatile organic compounds (VOCs). The barrier can be positioned above or below a solid concrete ground floor slab or above a precast suspended segmental ground floor system, e.g. beam and block floor.

The barrier can also be used in all types of buildings to prevent the ingress of harmful levels of ground gases e.g. methane, carbon dioxide and radon. The barrier also acts as a damp proof membrane. In this application, the barrier can be positioned above or below a solid concrete ground floor slab or above a precast suspended segmental ground floor system, e.g. beam and block floor.

The product is not intended for use where there is a risk of hydrostatic pressure.


System components

- Visqueen Ultimate Double Sided Jointing Tape, 100mm x 15m
- Visqueen GR Lap Tape, 150mm x 10m
- Visqueen Ultimate Top Hat Units
- Visqueen Preformed Units
- VisqueenPro Detailing Strip, 300mm x 10m, 500mm x 10m

Find your local stockist



GAS MITIGATION MEASURES PLAN



The gas membrane validation photographs are enclosed within this letter. For information, Table 1 includes references and validation dates of previously validated plots.

TABLE 1 – VALIDATION LETTER REFERENCE

PLOT NUMBER	DATE	REPORT NUMBER
1	3 rd March 2022	V4
2	3 rd March 2022	V4
3	3 rd March 2022	V4
4	29 th March 2022	V5
5	29 th March 2022	V5
6		
7		
8		
9		
10		
11		

PLOT NUMBER	DATE	REPORT NUMBER
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		
31		
32		
33		
34		
35		

PLOT NUMBER	DATE	REPORT NUMBER
36		
37		
38		
39		
40		
41		
42		
43		
44		
45		
46		
47		
48		
49		
50		
51		
52		
53		
54		
55		
56		
57		
58		
59		

PLOT NUMBER	DATE	REPORT NUMBER
60		
61		
62		
63		
64		
65		
66		
67		
68		
69		
70		
71		
72		
73		
74		
75		
76		
77		
78		
79		
80		
81		
82		
82		

PLOT NUMBER	DATE	REPORT NUMBER
83		
84		
85		
86	27 th May 2022	V9
87	27 th May 2022	V9
88	27 th May 2022	V9
89	25 th May 2022	V8
90	25 th May 2022	V8
91	25 th May 2022	V8
92	8 th June 2022	V12
93	8 th June 2022	V12
94	28 th June 2022	V15
95	28 th June 2022	V15
96		
97		
98		
99	30 th May 2022	V10
100	31 st May 2022	V11
101	31 st May 2022	V11
102	15 th June 2022	V13
103	15 th June 2022	V13
104	22 nd June 2022	V14
105	22 nd June 2022	V14
106		

PLOT NUMBER	DATE	REPORT NUMBER
107		
108	4 th July 2022	V15
109	4 th July 2022	V15
110	19 th July 2022	V18
111		
112		
113		
114		
115		
116		
117		
118		
119		
120		
121		
122		
123		
124		
125	8 th September 2022	V23
126	8 th September 2022	V23
127	8 th September 2022	V23
128	8 th September 2022	V23
129	8 th September 2022	V23
130	23 rd August 2022	V20

PLOT NUMBER	DATE	REPORT NUMBER
131	23 rd August 2022	V20
132	23 rd August 2022	V20
133	23 rd August 2022	V20
134	5 th September 2022	V21
135	15 th September 2022	V25
136	23 rd August 2022	V20
137	23 rd August 2022	V20
138	23 rd August 2022	V20
139	23 rd August 2022	V20
140	4 th August 2022	V19
141	15 th July 2022	V17
142	15 th July 2022	V17
143	11 th July 2022	V16
144	11 th July 2022	V16
145	11 th July 2022	V16
146	9 th May 2022	V6
147	9 th May 2022	V6
148	9 th May 2022	V6
149	9 th May 2022	V6
150	13 th May 2022	V7
151	9 th May 2023	V43
152	9 th May 2023	V43
153	2 nd June 2023	V44
154	2 nd June 2023	V44

PLOT NUMBER	DATE	REPORT NUMBER
155	8 th June 2023	V46
156	8 th June 2023	V46
157		
158		
159	19 th July 2023	V48
160	19 th July 2023	V48
161	2 nd August 2023	V50
162	9 th August 2023	V51
163	7 th February 2023	V40
164	7 th February 2023	V40
165	7 th February 2023	V40
166	7 th February 2023	V40
167	4 th November 2022	V31
168	24 th September 2022	V26
168	24 th September 2022	V26
169		
170	5 th October 2022	V27
171	21 st November 2022	V33
172	21 st November 2022	V33
173	23rd November 2022	V34
174	12 th December 2022	V35
175	12 th December 2022	V35
176	15 th December 2022	V36
177	15 th December 2022	V36

PLOT NUMBER	DATE	REPORT NUMBER
178	4 th November 2022 10 th November 2022	V31 V32
179	4 th November 2022	V31
180	4 th November 2022	V31
181	27 th October 2022	V30
182	27 th October 2022	V30
183	27 th October 2022	V30
184	24 th October 2022	V29
185	24 th October 2022	V29
186	24 th October 2022	V29
187	24 th October 2022	V29
188		
189	21 st November 2022	V33
190	21 st November 2022	V33
191	1 st September 2022	V22
192	1 st September 2022	V22
193	1 st September 2022	V22
194	22 nd September 2022	V24
195	22 nd September 2022	V24
196	24 th September 2022	V26
197	24 th September 2022	V26
198	12 th October 2022	V28
199	12 th October 2022	V28
200	24 th October 2022	V29
201	24 th October 2022	V29

PLOT NUMBER	DATE	REPORT NUMBER
202	24 th October 2022	V29
203	24 th October 2022	V29
204	23 rd February 2023	V40
205	23 rd February 2023	V40
206	23 rd February 2023	V40
207	23 rd February 2023	V40
208	1 st March 2023	V41
209	1 st March 2023	V41
210		
211		
212		
213		
214	30 th October 2023	V58
215	27 th September 2023	V56
216	27 th September 2023	V56
217	13 th September 2023	V55
218	13 th September 2023	V55
219	13 th September 2023	V55
220	27 th April 2023	V42
221	27 th April 2023	V42
222	27 th April 2023	V42
223	22 nd August 2023	V53
224	18 th August 2023	V52
225	9 th August 2023	V51

PLOT NUMBER	DATE	REPORT NUMBER
226	27 th July 2023	V49
227	27 th July 2023	V49
228	19 th July 2023	V48
229	19 th July 2023	V48
230	7 th July 2023	V47
231	7 th July 2023	V47
232		
233		
234	4 th September 2023	V54
235	4 th September 2023	V54
236	24 th Jan 2022	V1
237	24 th Jan 2022	V1
238	24 th Jan 2022	V1
239	24 th Jan 2022	V1
240	18 th May 2023	V44
241	18 th May 2023	V44
242	15 th February 2022	V3
243	15 th February 2022	V3
244		
245		
246	24 th January 2022	V2
247	24 th January 2022	V2
248		
249		

PLOT NUMBER	DATE	REPORT NUMBER
250		
Apartment Block 1	15 th September 2022	V25
	5 th October 2022	V27
Apartment Block 1 Stairwell	19 th January 2023	V38
	20 th January 2023	V39
Apartment Block 2	23 rd August 2022	V20

GAS MEMBRANE VALIDATION

Complete

Site Name	Belle Vue
Location	23 Fairground Road Manchester England M18 United Kingdom (53.46099236769775, - 2.185541867133633)
Project Manager	Nicola Sellars
Project number	12123
Developer	Countryside
Site representative Signature	30 Oct 2023 1:15 PM GMT
Conducted on	30 Oct 2023 1:11 PM GMT
Prepared by	Joe Newall

Inspection Gas Membrane

Plot Inspection

Plot Inspection 1

Plot Number

214

Type of Development: Other add note

House

Foundation Type: Other add note

Suspended Floor

Gas Membrane Type: Manufacturer, gauge, and colour.

Gold Visqueen

Gas Membrane Condition: Open punctures, tears, rips, stretching, Presence of debris, Repairs, Signs of weakness such as raised or sunken indentations, Protection plan in place to restrict access to lain gas membrane? IF FAIL DESCRIPTION IN ACTIONS AND PHOTOS REQUIRED

Pass



Photo 1



Photo 2



Photo 3



Photo 4

Laps, welds, and joints seals: Joints lapped and sealed in accordance with manufacturer's requirements/ specification? Minimum overlap insured? Sections taped twice? Are welds complete? Appropriate joining/double-sided tape used, Folds running in line with joints? (no joints cutting across folds)

Pass



Photo 5



Photo 6

Service entries seals: Top hats seal arrangements fixed around service entries? Use of Jubilee clips?

Yes



Photo 7




Photo 8




Photo 9




Photo 10



Photo 11




Photo 12



Photo 13

Type of joints/ Lapping

Taped

Corners / Internal joints: Check all corners are correctly formed or contractor has used preformed corners.

Pass




Photo 14



Photo 15



Photo 16



Photo 17

Extent of Coverage: Is the membrane covering the entire plot?
Does membrane span over outside walls?

Yes



Photo 18



Photo 19



Photo 20

Condition of sub-grade and underside of gas membrane: Check that the subgrade does not contain rough/uneven surfaces, is appropriately clean and that there are no hard/sharp objects. That protective sand blinding or geotextile (if specified) is present and meets the design criteria.

Pass

Slab / membrane condition (is membrane clear of debris or insulation): Can membrane be fully seen and photographed – ask contractor to remove an debris so membrane can be fully seen an inspected – this is a requirement of NHBC and local authorities.

Pass

External Wall Air bricks: Numbers, size. positions as design drawing? (Minimum of 3 walls)

Pass



Photo 21



Photo 22



Photo 23

Passive Venting

Sub-floor Void: Is a check possible on future plots (insert Plot number or NO in text box)

NO

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8




Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23