



E3P
Taylor Road
Trafford Park
Urmston
Manchester
M41 7JQ

info@E3P.co.uk
www.E3P.co.uk

GAS MEMBRANE VALIDATION

Site Name: Belle Vue	Project Number: 12-123
Company Name: Countryside Properties	Date: 27-10-2022
Project Manager: S. Ellis	E3P Engineer: P. Lavelle
PM Qualifications: BSc (Hons), FGS, Cenv	Engineer Qualifications: GGS Gas training Feb 22
Ground Gas Risk Assessment: Amber 1	
<p>Overview: The membrane comprised a Visqueen low permeability gas membrane (Yellow) resistant to radon, carbon dioxide and low levels of methane. E3P can confirm there were no holes or rips at the time of inspection. Upon being laid the membrane is to be covered with a Celotex (closed Cell) floor insulation material which is considered to provide a high degree of protection.</p> <p>All external joints were inspected and E3P can confirm that the membrane was overlapped and double taped to external and internal gas resistant DPM. The membrane was taped to the gas resistant DPM using a double-sided jointing tape. All the overlaps were then additionally taped using foil backed girth tape.</p> <p>Each unit has a service duct located to the front and outer edge of the property. E3P inspected each one and can confirm that the top-hats have been adequately sealed against the membrane.</p> <p>Based on the information provided within this report, the site inspections and validation checklists, E3P can confirm that Plots 181-183 have been installed with gas protection measures in accordance with Amber 1 to an acceptable level of workmanship.</p>	

GAS MEMBRANE VALIDATION

Complete

Score	100%
-------	------

Site Name	Belle Vue
-----------	-----------

Location	Belle Vue Greyhound Stadium, Kirkmanshulme Lane Manchester England M18 7BD United Kingdom (53.461446598944846, -2.18399460069138)
----------	---

Project Manager	Stuart Ellis
-----------------	--------------

Project number	12123
----------------	-------

Developer	Countryside
-----------	-------------

Site representative Signature	Paul Lewis 27 Oct 2022 3:36 PM BST
-------------------------------	---------------------------------------

Conducted on	27 Oct 2022 3:20 PM BST
--------------	-------------------------

Prepared by	Patrick Lavelle
-------------	-----------------

Inspection Gas Membrane - 100%	100%
Plot Inspection - 100%	100%
Plot Inspection 1 - 100%	100%
Plot Number	181
Type of Development: Other add note	House
	
Photo 1	
Gas Characteristic Situation	CS2
Foundation Type: Other add note	Suspended Floor
Gas Membrane Type: Manufacturer, gauge, and colour.	Yellow visqueen brand not stated
	
Photo 2	
Gas Membrane Condition: Open punctures, tears, rips, stretching, Presence of debris, Repairs, Signs of weakness such as raised or sunken indentations, Protection plan in place to restrict access to lain gas membrane? IF FAIL DESCRIPTION IN ACTIONS AND PHOTOS REQUIRED	Pass
	
Photo 3	
	
Photo 4	
	
Photo 5	
Laps, welds, and joints seals: Joints lapped and sealed in accordance with manufacturer's requirements/ specification? Minimum overlap insured? Sections taped twice? Are welds complete? Appropriate joining/double-sided tape used, Folds running in line with joints? (no joints cutting across folds)	Pass



Photo 6




Photo 7



Photo 8



Photo 9




Photo 10



Photo 11

Service entries seals: Top hats seal arrangements fixed around service entries? Use of Jubilee clips?

Yes



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22

Type of joints/ Lapping

Taped

Corners / Internal joints: Check all corners are correctly formed or contractor has used performed corners.

Pass



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33

Extent of Coverage: Is the membrane covering the entire plot? Does membrane span over outside walls?

Yes



Photo 34

Photo 35

Photo 36

Condition of sub-grade and underside of gas membrane:
Check that the subgrade does not contain rough/uneven surfaces, is appropriately clean and that there are no hard/sharp objects. That protective sand blinding or geotextile (if specified) is present and meets the design criteria.

Pass

Slab / membrane condition (is membrane clear of debris or insulation): Can membrane be fully seen and photographed – ask contractor to remove an debris so membrane can be fully seen an inspected – this is a requirement of NHBC and local authorities.

Pass



Photo 37

Plot Inspection 2 - 100%

100%

Plot Number

182

Type of Development: Other add note

House



Photo 38

Gas Characteristic Situation

CS2

Foundation Type: Other add note

Suspended Floor

Gas Membrane Type: Manufacturer, gauge, and colour.

Yellow visqueen brand not stated



Photo 39

Gas Membrane Condition: Open punctures, tears, rips, stretching, Presence of debris, Repairs, Signs of weakness such as raised or sunken indentations, Protection plan in place to restrict access to lain gas membrane? IF FAIL DESCRIPTION IN ACTIONS AND PHOTOS REQUIRED

Pass



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44

Laps, welds, and joints seals: Joints lapped and sealed in accordance with manufacturer's requirements/ specification? Minimum overlap insured? Sections taped twice? Are welds complete? Appropriate joining/double-sided tape used, Folds running in line with joints? (no joints cutting across folds)

Pass



Photo 45

Photo 46

Photo 47

Service entries seals: Top hats seal arrangements fixed around service entries? Use of Jubilee clips?

Yes



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56



Photo 57




Photo 58



Photo 59



Photo 60

Type of joints/ Lapping

Taped

Corners / Internal joints: Check all corners are correctly formed or contractor has used performed corners.

Pass



Photo 61



Photo 62



Photo 63



Photo 64



Photo 65



Photo 66



Photo 67



Photo 68



Photo 69



Photo 70



Photo 71

Extent of Coverage: Is the membrane covering the entire plot? Does membrane span over outside walls?

Yes



Photo 72

Photo 73

Photo 74

Condition of sub-grade and underside of gas membrane:
Check that the subgrade does not contain rough/uneven surfaces, is appropriately clean and that there are no hard/sharp objects. That protective sand blinding or geotextile (if specified) is present and meets the design criteria.

Pass

Slab / membrane condition (is membrane clear of debris or insulation): Can membrane be fully seen and photographed – ask contractor to remove an debris so membrane can be fully seen an inspected – this is a requirement of NHBC and local authorities.

Pass



Photo 75

Photo 76

Photo 77

Plot Inspection 3 - 100%

100%

Plot Number

183

Type of Development: Other add note

House



Photo 78

Gas Characteristic Situation

CS2

Foundation Type: Other add note

Suspended Floor

Gas Membrane Type: Manufacturer, gauge, and colour.

Yellow visqueen brand not stated

Gas Membrane Condition: Open punctures, tears, rips, stretching, Presence of debris, Repairs, Signs of weakness such as raised or sunken indentations, Protection plan in place to restrict access to lain gas membrane? IF FAIL DESCRIPTION IN ACTIONS AND PHOTOS REQUIRED

Pass



Photo 79



Photo 80



Photo 81



Photo 82

Laps, welds, and joints seals: Joints lapped and sealed in accordance with manufacturer's requirements/ specification? Minimum overlap insured? Sections taped twice? Are welds complete? Appropriate joining/double-sided tape used, Folds running in line with joints? (no joints cutting across folds)

Pass



Photo 83



Photo 84



Photo 85



Photo 86



Photo 87



Photo 88



Photo 89



Photo 90

Service entries seals: Top hats seal arrangements fixed around service entries? Use of Jubilee clips?

Yes



Photo 91



Photo 92



Photo 93



Photo 94



Photo 95



Photo 96



Photo 97



Photo 98



Photo 99



Photo 100



Photo 101




Photo 102



Photo 103



Photo 104

Type of joints/ Lapping

Taped

Corners / Internal joints: Check all corners are correctly formed or contractor has used performed corners.

Pass



Photo 105



Photo 106



Photo 107




Photo 108



Photo 109



Photo 110



Photo 111



Photo 112



Photo 113



Photo 114



Photo 115

Extent of Coverage: Is the membrane covering the entire plot? Does membrane span over outside walls?

Yes



Photo 116



Photo 117



Photo 118



Photo 119



Photo 120

Condition of sub-grade and underside of gas membrane: Check that the subgrade does not contain rough/uneven surfaces, is appropriately clean and that there are no hard/sharp objects. That protective sand blinding or geotextile (if specified) is present and meets the design criteria.

Pass

Slab / membrane condition (is membrane clear of debris or insulation): Can membrane be fully seen and photographed – ask contractor to remove an debris so membrane can be fully seen an inspected – this is a requirement of NHBC and local authorities.

Pass



Photo 121



Photo 122



Photo 123



Photo 124

Passive Venting

Sub-floor Void: Is a check possible on future plots (insert Plot number or NO in text box)

No

External Wall Air bricks: Numbers, size. positions as design drawing? (Minimum of 3 walls)

Pass



Photo 125



Photo 126



Photo 127



Photo 128

Appendix



Photo 1



Photo 2



Photo 3



Photo 4




Photo 5



Photo 6



Photo 7




Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45



Photo 46




Photo 47



Photo 48



Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54



Photo 55



Photo 56



Photo 57



Photo 58



Photo 59



Photo 60



Photo 61



Photo 62



Photo 63



Photo 64



Photo 65



Photo 66



Photo 67



Photo 68



Photo 69



Photo 70



Photo 71



Photo 72



Photo 73



Photo 74



Photo 75



Photo 76



Photo 77



Photo 78



Photo 79



Photo 80



Photo 81



Photo 82



Photo 83



Photo 84




Photo 85



Photo 86



Photo 87



Photo 88



Photo 89



Photo 90



Photo 91



Photo 92



Photo 93



Photo 94



Photo 95



Photo 96



Photo 97



Photo 98



Photo 99



Photo 100



Photo 101



Photo 102



Photo 103



Photo 104



Photo 105



Photo 106



Photo 107



Photo 108



Photo 109



Photo 110



Photo 111



Photo 112



Photo 113



Photo 114



Photo 115



Photo 116



Photo 117



Photo 118



Photo 119



Photo 120



Photo 121



Photo 122



Photo 123



Photo 124



Photo 125



Photo 126



Photo 127



Photo 128