

**GHR05 and GHR06
flashing locations at
wall abutments**

GHR05 (south-west)

Chase in stone joint

Revision: -
First issue
Date: 26 September 2024

Page 1 of 8

OTH-PUR-TH-RF-SKE-A-3816

**GHR05 and GHR06
flashing locations at
wall abutments**

GHR05 (south-west)



Revision: -
First issue
Date: 26 September 2024

Page 2 of 8

OTH-PUR-TH-RF-SKE-A-3816

**GHR05 and GHR06
flashing locations at
wall abutments**

GHR05 (North-west)

Chase below coping

Revision: -
First issue
Date: 26 September 2024

Page 3 of 8

OTH-PUR-TH-RF-SKE-A-3816

**GHR05 and GHR06
flashing locations at
wall abutments**

GHR05 (North-west)

Chase below coping

Vertical chase

75

Chase follows original lead

75

Chase at interface
between tile and
stone (chase into
tile leaving stone
untouched)

Revision: -
First issue
Date: 26 September 2024

Page 4 of 8

OTH-PUR-TH-RF-SKE-A-3816

**GHR05 and GHR06
flashing locations at
wall abutments**

GHR06 (South-east)

Chase in stone joint

Revision: -
First issue
Date: 26 September 2024

Page 5 of 8

OTH-PUR-TH-RF-SKE-A-3816

**GHR05 and GHR06
flashing locations at
wall abutments**

GHR06 (South-east)

Chase in stone joint

75

75

Revision: -
First issue
Date: 26 September 2024

Page 6 of 8

OTH-PUR-TH-RF-SKE-A-3816

**GHR05 and GHR06
flashing locations at
wall abutments**

GHR06 (North-east)




**Revision: -
First issue
Date: 26 September 2024**

Page 7 of 8

OTH-PUR-TH-RF-SKE-A-3816

**GHR05 and GHR06
flashing locations at
wall abutments**

GHR06 (North-east)



Chase below coping

Revision: -
First issue
Date: 26 September 2024

Page 8 of 8

OTH-PUR-TH-RF-SKE-A-3816