Dantzic - Summary of Design Development and Approved/ Proposed Drawings

	Item	Justification	Approved Planning dwg references PP Ref: 117384/FO/2017 and LBC Ref: 117385/LO/2017	Amended dwg references	Additional Proposed Supporting Statements	Date Agreed Agreement with MCC	Notes
1	Buff brick repair	Buildability	NOMA.DANTZIC.Conservation Strategy.Externals.SLHA 2017.08.24 REV A		NOMA.DANTZIC.Conservation Strategy.Externals.SLHA.2018.05.03.REVC	07/03/2018	Conservation strategy updated to reflect buff brick repair strategy. No change to approved drawing.
2	Revised floor finishes	Design Development	5814-43-801 A 5814-43-802 A 5814-43-803 A 5814-43-804 A 5814-43-805 A 5814-43-806 A 5814-43-807 A 5814-43-808 A 5814-43-809 A	5814-43 -801 B 5814-43 -802 B 5814-43 -803 B 5814-43 -804 B 5814-43 -805 B 5814-43 -806 B 5814-43 -807 B 5814-43 -808 B 5814-43 -809 B		11/05/2018	Approved drawings updated to reflect change.
3	WC on Lower Ground	Consistency	5814-20- 802 A	5814-20-801 B 5814-20-802 C		16/04/2018	Approved drawing updated to reflect change and aditional drawing submitted to show changes to lower ground (change to level 1 and 2)
4	Reduction of riser cupboard area to new stair	Design Development	5814-20-801 A 5814-20-802 A 5814-20-803 B 5814-20-804 A 5814-20-805 A 5814-20-806 A 5814-20-807 A 5814-20-807 A 5814-20-808 B 5814-20-809 A	5814-20-801 B 5814-20-802 C 5814-20-803 C 5814-20-804 B 5814-20-805 B 5814-20-806 B 5814-20-807 B 5814-20-808 C 5814-20-809 C 5814-20-810 D		16/04/2018	Approved drawing updated to reflect change.
5	Level 2 lobby now only partially retained (rather than complete removal)	Design Development	NOMA.DANTZIC.ConservationStrategy.Partitions.SLHA.2017.08.24	5814-22-402 A 5814-01-102 F	NOMA.DANTZIC.ConservationStrategy.Partitions.SLHA.2017.08.24.REV.A.2018.03.06	12/04/2018	Conservation strategy updated to reflect strategy to partially retain lobby. Additional plans submitted to show detail of fixings/ repair
6	Brick up of roof where lintel has failed	Design Development	5814-20-810 C	5814-20-810 D		12/04/2018	
7	Repair of steel lintel failures at level 9 and the main roof parapet	Design Development	5814-20-825 C 5814-20-826 C 5814-20-827 C	Heritage mark up - 008 - Full Survey Heritage mark up - 008 - Level 9	NOMA.DANTZIC.Conservation Strategy.Externals.SLHA.2018.02.19.REVC Dantzic Lintel Survey	16/04/2018	Conservation Strategy updated and supplementary information submitted to refelct repair strategy. No change to approved drawing.
8	Removal and repair of brickwork on level 10	Design Development	5814-20-825 C 5814-20-826 C 5814-20-827 C	Heritage mark up - 010 - Investigation of cracked brickwork L10	NOMA.DANTZIC.Conservation Strategy.Externals.SLHA.2018.05.03.REVC	16/04/2018	Conservation Strategy updated and supplementary information submitted to reflect repair strategy. No change to approved drawing.
9	L8 hand rail repair	Design Development	5814-20-825 C 5814-20-826 C 5814-20 827 C		NOMA.DANTZIC.Conservation Strategy.Externals.SLHA.2018.05.03.REVC	08/10/2018	Conservation Strategy updated to reflect repair strategy. No change to approved drawing.

10	Asbestos Removal and ceiling repair	Design Development	5814-35-803 5814-35-804 5814-35-808 5814-35-809	5814-35-205 5814-35-501 B 5814-SK-152 5814-SK-153 5814-SK-154 5814-SK-155 5814-SK-156 5814-SK-157 5814-SK-158	Planning Supplement Asbestos Removal SHLA 10.05.2018 REV A Heritage mark up - 013 - Ceiling removal Rev 1	29/06/2018	Approved drawings updated and additional drawings submitted to reflect additional asbestos found in places previously not identified at submission stage.
11	Gas Main Alteration	Buildability	n/a		Methodology for Moving Federation Gas Main repaired by Russells Construction referenced 014	19/06/2018	Supplementary information submitted to show gas main alternation. No change to approved drawings.
12	Roof Drip Detail	Design Development	5814-27-803 5814-27-806		Methodology Installation of New Drip Detail on Main Roof prepared by Russells Construction referenced 015	19/06/2018	Supplementary information submitted to show roof drip detail. No change to approved drawings.
13	Atrium Crack Brick Repair	Design Development	NOMA.DANTZIC.Conservation Strategy.Externals.SLHA 2017.08.24 REV A		Dantzic Building supplementary planning note - atrium brickwork repairs 2018.06.11 prepared by SLHA and method for atrium crack repair prepared by Russells Construction referenced 016	19/06/2018	Conservation Strategy updated and supplementary information submitted to reflect repair strategy. No change to approved drawing.
14	Parquet re-use /raised floor access	Design Development	5814-33-803 5814-33-801	HC-17204- (SK)-04 5814-33-801 A 5814-33-803 A		27/09/2018	Approved drawing updated and additional drawing provided to show detail of raised floor access.
15	lobby change around the goods lift at level 2	Design Development	5814-20-802	5814-20-803 C		08/10/2018	Approved drawing updated to relect change.
16	Reception design fit out and finishes	Design Development	5814-43-803 A	5814-43-803 B	Stage 3 Developed Interior Design prepared by Sheppard Robson May 2018	23/01/2018	Approved drawing updated to relect change and supplementary interior design submitted to show visualisations of fit out and finishes.
17	Repositioning of door to Level 3 Office from reception	Design Development	5814-20-803 B	5814-20-803 C		08/10/2018	Approved drawing updated to relect change
18	Level 3 WC Flooring	Design Development	5814-43-803 A	5814-20-803 C		08/10/2018	Approved drawing updated to relect change
19	Materials/ finishes surrounding Dantzic Stair	Buildability	5814-24-830	5814-24-630 F 5814-24-504 B		23/01/2019	Approved drawing updated to relect change and additional drawing submitted to show detail.
20	Amendment to the opening mechanism of the main entrance doors	Buildability	5814-20-841 B	5814-21-620 C		23/01/2019	Approved drawing updated to relect change