



Photograph of window head




Photograph of defective lintel

Rusting and sagging angle lintel to be removed once temporary propping is in place. To be replaced with angle lintel of similar size (tbc once one is removed). Replacement lintel will be stainless steel to avoid a repeat of the corrosion. These will be primed and painted RAL9001 to match windows. See full survey for extent of problem.

Bricks to be carefully removed with hand tools to prevent damage to surrounding bricks. These will allow the exisiting lintel to be removed. Bricks to be reinstated once new lintel is installed. This will happen to both sides of the window.



Photograph of defective mortar joint



Photograph of window cill

Dantzic - Methodology for removal of existing lintels from level 9 windows

Russells Construction