




Window 9.01 - 20mm - Approx sag 7mm




Window 9.02 - 21mm - Approx sag 8mm



Window 9.03 - 16mm - Approx sag 3mm




Window 9.04 - 15mm - Approx sag 2mm



Window 9.05 - 15mm - Approx sag 2mm


KEYPLAN



Dantzic - Methodology for removal of existing lintels from level 9 windows - Full survey - Page 1 of 3

PA 14/4/18

RCL DANTZIC HERITAGE MARK UP - 008 - FULL SURVEY





Window 9.06 - 17mm - Approx sag 4mm



Window 9.07 - 20mm - Approx sag 7mm



Window 9.08 - 30mm - Approx sag 17mm



Window 9.09 - 24mm - Approx sag 11mm



Window 9.10 - 20mm - Approx sag 7mm



Window 9.11 - 28mm - Approx sag 15mm



Window 9.12 - 24mm - Approx sag 11mm



Window 9.13 - 23mm - Approx sag 10mm



Window 9.14 - 22mm - Approx sag 9mm




Window 9.16 - 30mm - Approx sag 17mm




Window 9.15 - 26mm - Approx sag 13mm

KEYPLAN



Dantzic - Methodology for removal of existing lintels from level 9 windows - Full survey - Page 2 of 3

Russells Consultants






Window 9.17 - 20mm - Approx sag 7mm



Window 9.18 - 14mm - Approx sag 1mm



Window 9.19 - 23mm - Approx sag 10mm




Window 9.20 - 13mm - Approx sag 0mm



Window 9.21 - 14mm - Approx sag 1mm

KEYPLAN



Dantzic - Methodology for removal of existing lintels from level 9 windows **-** Full survey **-** Page 3 of 3

Russells Conveyancers