Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



01. Pillar A.JPG



02. Pillar B.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



03. Opening behind pillar B.JPG



04. Inverted bracket C.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



05. Inverted bracked D.JPG



06. Inverted bracket C.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



07. Defective roof abutment to pillar C.JPG



08. Inverted bracket D.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



09. Defective mortar joints.JPG



10. Inverted bracket E.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



11. Faience requires repointing.JPG



12. Roof abutment to bracket F.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



13. Blocked gutters to be cleared.JPG



14. Inverted bracket G.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



15. Mortar joints require repointing.JPG



16. Mortar joints require repointing.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



17. Previous flashband repairs to be removed (1).JPG



18. Previous flashband repairs to be removed (2).JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



19. Inverted bracked H - repointing required.JPG



20. Defective roof abutment.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



21. Defective roof abutment.JPG




22. Defective roof abutment.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



23. Defective roof abutment.JPG



24. Crudely repaired capitals to be replaced.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



25. Sample of new faience compared to existing.JPG



26. Defective timber to be replaced.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



27. First Floor Sliding Sash Window.png



28. Frame of sliding sash windows are rotten.png

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



29. Sliding sash windows difficult to operate.png



30. Sash windows cannot be opened more than a few inches.png

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



31. Timber frames have deteriorated due to lack of decoration.png



32. Windows to bay window are in the worst condition.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



33. Windows to bay window are in the worst condition.JPG



34. Windows to bay window are in the worst condition.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



35. Windows are beyond economical repair.JPG



36. Windows are beyond economical repair.JPG

Photographic Schedule - Beswick Co-op, 95-97 Northmoor Road



37. Some windows cannot be opened.JPG